

Blank or Unassigned cost estimate cells indicate further design requirements or modification by original vendor.

Facility	Record Number	Category	Item	Estimated Cost	Code Reference	Progress	Projected Completion Date	Actual Completion Date	Actual Cost
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18793	Parking	Less Than Minimum Required Parking Spaces	\$370.00	ADA 208, 208.2, CA 11B-208.2	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18794	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18795	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18796	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18797	Parking	ISA is Faded or Damaged	\$117.00	ADA 502, CA 11B-502.6.4	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18798	Parking	Van Accessible Signage	\$250.00	ADA 502, 502.6	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18799	Parking	Access Aisle Width	\$250.00	ADA 208, 502.2	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18800	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18801	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18802	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18803	Parking	ISA is Faded or Damaged	\$117.00	ADA 502, CA 11B-502.6.4	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18857	Curb Ramps	Projects into Traffic	\$1,400.00	ADA 406, 406.4, 406.5	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18858	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18859	Curb Ramps	Right Side Flare Slope	\$1,300.00	ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18860	Curb Ramps	Grooved Borders	\$248.00	CA 11B-406.5.11	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18819	Path of Travel	Sidewalk Width	\$3,500.00	ADA 403.5.1, CA 11B-403.5.1	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18820	Path of Travel	Designated Accessible Route	\$1,840.00	ADA 206, 206.2, 402.1	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18833	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18849	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18906	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/26		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18821	Ramps	Ramp Run Cross Slope	\$3,600.00	ADA 403, 405.3, CA 11B-405.3	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18822	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18823	Ramps	Handrail Extension Length	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18824	Ramps	Handrail Extension Length	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18825	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18826	Ramps	Ramp Run Cross Slope	\$3,600.00	ADA 403, 405.3, CA 11B-405.3	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18827	Ramps	Landing Length	\$2,600.00	ADA 405.7, 405.7.4	Not_Started	12/31/31		\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18828	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31		\$0.00

American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18850	Ramps	Ramp Run Length	\$3,168.00	ADA 405, 405.6	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18851	Ramps	Landing Change in Level	\$1,840.00	ADA 302, 303, 303.3, 405.7.1, CA 118-303, 405	Not_Set	12/31/23	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18852	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 118-405.7.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18853	Ramps	Handrail Extension Length	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 118-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18854	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 118-405.8, 505.4	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18855	Ramps	Handrail Extension Length	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 118-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18856	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 118-405.8, 505.4	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18829	Stairs	Risers Height		ADA 504.2, CA 118-504.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18830	Stairs	Riser Striping	\$944.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18831	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 118-504.6, 505	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18832	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 118-504.6, 505	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18862	Stairs	Middle Handrail	\$1,528.00		Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18863	Stairs	Riser Striping	\$944.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18864	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18865	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 118-505.10.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18866	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 118-504.6, 505.10	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18867	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 118-505.10.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18868	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 118-505.10.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18869	Stairs	Handrail on Left or Right Side	\$2,200.00	ADA 504.6, 505.2, CA 118-504.6, 505.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18870	Stairs	Riser Striping	\$944.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18871	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 118-504.6, 505.10	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18872	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 118-504.6, 505	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18887	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 118-206.2, 210, 402.2, 504	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18888	Stairs	Handrails	\$1,528.00	ADA 504, 504.6, 505.2, CA 118-504.6, 505.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18889	Stairs	Riser Striping	\$944.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18904	Stairs	Risers Height		ADA 504.2, CA 118-504.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18905	Stairs	Riser Striping	\$944.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18846	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18844	Doors	Door Opening Pressure	\$75.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18847	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00

American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18848	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18810	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18809	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18808	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/21	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18843	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18842	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/21	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18891	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18890	Doors	Hardware	\$340.00	ADA 404.2.7, CA 118-404.2.7	Not_Started	12/31/21	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18903	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/21	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18804	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18885	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18811	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18886	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18902	Signage	Room Identification	\$474.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18907	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18861	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18873	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18874	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18816	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18812	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 118-213, 309.4, 606	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18813	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18814	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18815	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18817	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18818	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18834	Restrooms	Clear Space in Front of Compartment	\$4,000.00	ADA 404.2, 603, 604.8.1.2, CA 118-404.2, 604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18840	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18841	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18838	Restrooms	Grab Bar Distance From Back Wall	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18839	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/26	\$0.00

American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18835	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18837	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18875	Restrooms	Clear Space in Front of Compartment	\$4,000.00	ADA 603, 604.8.1.2, CA 11B-604.8.1.2, 604.8.2.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18882	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18883	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18884	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18880	Restrooms	Grab Bar Distance From Back Wall	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18881	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 11B-609.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18876	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18878	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18879	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18892	Restrooms	Required Alternate Stall	\$4,000.00	ADA 213, 213.3.1, 604	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18899	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18901	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18893	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 11B-213, 309.4, 606	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18894	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18895	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18896	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18897	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18898	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18900	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18805	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18806	Drinking Fountains	Spout Height	\$627.00	ADA 211, 602, 602.4, CA 11B-602.4	Not_Started	12/31/31	\$0.00
American Legion Hall - 1021 South Santa Cruz Avenue Modesto, CA 95354	18807	Drinking Fountains	Alcove Width	\$2,500.00	ADA 305, 305.7, 602.2, CA 11B-602.9	Not_Started	12/31/31	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18920	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18922	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18921	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 11B-404.2.7	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18924	Doors	Open Doorway Height	\$5,600.00	ADA 307.4	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18936	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/25	\$0.00

Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18962	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18963	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18908	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18938	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18969	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18923	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/22	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18909	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18910	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18916	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18917	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18918	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18919	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18911	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18912	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 118-604.4	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18914	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 118-604.6	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18915	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18931	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18932	Restrooms	Urinal Rim Extension	\$951.00	ADA 605, 605.2, CA 118-605.2	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18930	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18926	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18927	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18928	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18929	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18933	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18934	Restrooms	Contrasting Finish	\$170.00	CA 118-703.7.2.6	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18935	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18925	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18944	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18947	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18940	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/25	\$0.00

Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18941	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18942	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18943	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18945	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18946	Restrooms	Contrasting Finish	\$170.00	CA 118-703.7.2.6	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18939	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Set	12/31/21	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18948	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18949	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18956	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18957	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18958	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18959	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 118-404, 604.8.1.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18954	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18955	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18960	Restrooms	Located Behind Front of Seat	\$230.00	ADA 604.7, CA 118-604.7	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18961	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 118-309.4, 609.3	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18950	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18951	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 118-604.4	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18953	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/25	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18964	Sinks	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 118-606.3	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18965	Sinks	Pipes Wrapping	\$149.00	ADA 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18966	Sinks	Toe Kick	\$420.00	ADA 305, 306, 606.2, CA 118-305, 306, 606.2	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18967	Sinks	Clear Floor Space Width	\$900.00	ADA 205, 228, 308, 309	Not_Set	12/31/26	\$0.00
Boy Scout Club House - 400 Enslin Avenue Modesto, CA 95354	18968	Sinks	Supply Lines	\$149.00	ADA 606.5, CA 118-606.5	Not_Set	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20648	Parking	Less Than Minimum Required Parking Spaces	\$370.00	ADA 208, 208.2, CA 118-208.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20683	Parking	Parking Lot Warning Sign Visibility	\$250.00	CA 118-502.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20684	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00	CA 118-502	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20649	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20650	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20651	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20652	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20653	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20655	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20656	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20657	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20658	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20659	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20660	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20661	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20662	Parking	Access Aisle Width	\$250.00	ADA 208, 502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20664	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20665	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20666	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20667	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20668	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20670	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20671	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20672	Parking	Access Aisle Striping	\$350.00	CA 11B-502.3.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20673	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20674	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20675	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20676	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20677	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20678	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20679	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20680	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20681	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20682	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20754	Parking	Required Minimum Van Accessible Spaces	\$370.00	ADA 208, 208.2.4, 502.7, CA 11B-208.2.4, 502.7	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20755	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20756	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20757	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20758	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20759	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20760	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20762	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20763	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20764	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20557	Curb Ramps	Projects into Traffic	\$1,400.00	ADA 406, 406.4, 406.5	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20558	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20559	Curb Ramps	Left Side Flare Slope	\$1,300.00	ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20560	Curb Ramps	Grooved Borders	\$248.00	CA 11B-406.5.11	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20566	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20567	Curb Ramps	Bottom Landing Slope	\$1,260.00	ADA 406, 406.2, CA 11B-406.5.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20568	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20717	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20719	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20718	Curb Ramps	Bottom Landing Slope	\$1,260.00	ADA 406, 406.2, CA 11B-406.5.8	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20833	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20834	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20583	Path of Travel	Carpet or Carpet Tile	\$659.00	ADA 302, 302.2, CA 11B-302.2, 403.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20562	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20561	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20569	Path of Travel	Designated Accessible Route	\$1,840.00	ADA 206, 206.2, 402.1	Not_Started	12/31/35	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20570	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/35	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20571	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20572	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20604	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20605	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20606	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20617	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20633	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20634	Path of Travel	Crosswalk Striping	\$300.00	ADA 705	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20632	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20737	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20741	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20772	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20773	Path of Travel	Crosswalk Striping	\$300.00	ADA 705	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20771	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20777	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20821	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20835	Path of Travel	Change in Level	\$300.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20776	Path of Travel	Mat or Runner	\$42.00	ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20827	Path of Travel	Mat or Runner	\$42.00	ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20554	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20555	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20573	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20601	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20630	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20631	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20641	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20733	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20735	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/30	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20734	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20564	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20565	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/26	\$0.00

Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20607	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20608	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20618	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20619	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20738	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20739	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20775	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20774	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20766	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20767	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20768	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20769	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20770	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20778	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20779	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20781	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20780	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20823	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20824	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20828	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20602	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20556	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20603	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20629	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20702	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20708	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20736	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20691	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/35	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20740	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue	Modesto, CA 95351	20765	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20831	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20596	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20597	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20598	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20599	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 118-404, 604.8.1.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20594	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20595	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20600	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20593	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 118-604.6	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20697	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20698	Restrooms	Urinal Rim Extension	\$951.00	ADA 605, 605.2, CA 118-605.2	Not_Set	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20693	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20694	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20695	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20696	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20699	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20700	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20692	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20703	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20704	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20705	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20707	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20706	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20712	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20713	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20714	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20715	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 118-404, 604.8.1.2	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20710	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20711	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20716	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20579	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20580	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20576	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20577	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20578	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20581	Restrooms	Door Signage	\$158.00	CA 118-216.8, 703.7.2.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20582	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20574	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20575	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 118-309.4, 603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20584	Restrooms	Back Wall Grab Bar	\$267.00	ADA 603, 604.5, 604.8.1.5, CA 118-604.5, 604.8.1.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20585	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20589	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1.1, 609, CA 118-604.5.1.1, 609	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20590	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20591	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 118-309.4, 609.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20586	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20588	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20613	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20614	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20616	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20611	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20612	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20615	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20609	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20610	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 118-309.4, 603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20625	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20626	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20627	Restrooms	Door Signage	\$158.00	CA 118-216.8, 703.7.2.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20622	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 118-213, 309.4, 606	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20623	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20624	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20628	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20620	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20621	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20635	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20638	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20639	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20640	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 11B-309.4, 609.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20637	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20642	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20645	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20646	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20647	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 11B-309.4, 609.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20644	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20685	Restrooms	Back Wall Grab Bar	\$267.00	ADA 603, 604.5, 604.8.1.5, CA 11B-604.5, 604.8.1.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20686	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20689	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20690	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 11B-309.4, 609.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20688	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20729	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20730	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20731	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20732	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20727	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20728	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20725	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20726	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20742	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20743	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20752	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20748	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20749	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20750	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20751	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 118-404, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20747	Restrooms	Grab Bar Distance From Back Wall	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20753	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 118-309.4, 609.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20744	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20746	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20789	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20790	Restrooms	Urinal Rim Extension	\$951.00	ADA 605, 605.2, CA 118-605.2	Not_Set		\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20788	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20785	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20786	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20787	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20791	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20782	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20783	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20784	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 118-309.4, 603.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20792	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20793	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20804	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20800	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20801	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20802	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20803	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20798	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20799	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20805	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00	ADA 603, 609.3, CA 118-309.4, 609.3	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20794	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20796	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 118-604.6	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20797	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20817	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20818	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20814	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20815	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20816	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20820	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20819	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20811	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20812	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 118-309.4, 603.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20813	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20701	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/24	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20721	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20722	Drinking Fountains	Stream Height	\$2,500.00	ADA 211, 602, 602.6, CA 118-211, 602	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20723	Drinking Fountains	Stream Trajectory	\$2,875.00	ADA 602.6, CA 118-602.6	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20724	Drinking Fountains	Clear Floor Space Slope	\$2,200.00	ADA 211, 305, 305.2, 306, 602, CA 118-602.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20547	Food Service	Minimum Required Seating	\$2,500.00	ADA 206, 226.1, 305, CA 118-226.1	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20548	Food Service	Table Knee Depth	\$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, CA 118-306.3.2, 306.3.3, 902.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20549	Food Service	Counter/Condiment/Tableware Height	\$2,500.00	ADA 902, 904.5, CA 118-904.4, 904.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20550	Food Service	Counter is a Protruding Object	\$250.00	ADA 307.2, 902, CA 118-307.2	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20551	Food Service	Counter/Condiment/Tableware Height	\$2,500.00	ADA 902, 904.5, CA 118-904.4, 904.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20552	Food Service	Counter is a Protruding Object	\$250.00	ADA 307.2, 902, CA 118-307.2	Not_Started	12/31/23	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20553	Food Service	Counter/Condiment/Tableware Height	\$2,500.00	ADA 902, 904.5, CA 118-904.4, 904.5	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20720	Food Service	Minimum Required Seating	\$2,500.00	ADA 206, 226.1, 305, 902	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20563	Emergency Warning Systems	Emergency Warning System	\$2,200.00	ADA 215, 702, CA 118-215, 702	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20830	Break/Conferenc e Room	Control Height		ADA 308	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20829	Break/Conferenc e Room	Tables - Knee Clearance	\$500.00	ADA 305, 306, 902.2, CA 118-305, 306, 902.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20832	Lockers	Accessible Lockers Availability	\$1,840.00	ADA 225.2.1, 811, CA 118-225.2.1, 811	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20825	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 118-305.2	Not_Started	12/31/22	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20826	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	12/31/26	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20806	Reach Ranges	Reach Ranges		ADA 204, 304, 307	Not_Started	12/31/31	\$0.00

Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20807	Reach Ranges	Element Highest Point of Operation	\$50.00 ADA 308, 309, CA 118-308, 309	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20808	Reach Ranges	Reach Ranges	ADA 204, 304, 307	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20809	Reach Ranges	Clear Floor Space Slope	\$500.00 ADA 304, CA 118-305.2	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20810	Reach Ranges	Element Highest Point of Operation	\$50.00 ADA 308, 309, CA 118-308, 309	Not_Started	12/31/31	\$0.00
Creekside Golf Course - 701 Lincoln Avenue Modesto, CA 95351	20822	Benches	Clear Floor Space	\$1,840.00 ADA 206, 305, 903.2, CA 118-206, 305, 903.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23538	Parking	Less Than Minimum Required Parking Spaces	\$370.00 ADA 208, 208.2, CA 118-208.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23539	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23540	Parking	Parking Space Length	\$350.00 CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23541	Parking	Parking Lot Warnings	\$300.00 CA 118-502.6.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23542	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 118-502.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23543	Parking	Van Accessible Signage	\$250.00 ADA 502, 502.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23544	Parking	Access Aisle Width	\$250.00 ADA 208, 502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23546	Parking	Access Aisle is Faded or Damaged	\$250.00 ADA 502.3, 502.3.3, CA 118-502.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23547	Parking	Access Aisle	\$180.00 CA 118-502.3.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23548	Parking	Access Aisle - "No Parking"	\$250.00 CA 118-502.3.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23549	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23550	Parking	Accessible Signage	\$250.00 ADA 502, 502.6, 703.7.2.1, CA 118-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23551	Parking	Must Travel Behind Parked Cars	\$1,100.00 ADA 502.3, CA 118-502.7.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23552	Parking	Parking Space Length	\$350.00 CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23553	Parking	Parking Lot Warnings	\$300.00 CA 118-502.6.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23554	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23555	Parking	Accessible Signage	\$250.00 ADA 502, 502.6, 703.7.2.1, CA 118-502.6, 703.7.2.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23556	Parking	Must Travel Behind Parked Cars	\$1,100.00 ADA 502.3, CA 118-502.7.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23557	Parking	Parking Space Length	\$350.00 CA 118-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23558	Parking	Parking Lot Warnings	\$300.00 CA 118-502.6.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23559	Parking	ISA is Faded or Damaged	\$117.00 ADA 502, CA 118-502.6.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23560	Parking	Access Aisle Width	\$350.00 ADA 502, 502.3.1, CA 118-502.3.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23561	Parking	Access Aisle	\$180.00 CA 118-502.3.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23562	Parking	Access Aisle - "No Parking"	\$250.00 CA 118-502.3.3	Not_Started	12/31/22	\$0.00

Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23563	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23564	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23565	Parking	ISA is Faded or Damaged	\$117.00 ADA 502, CA 11B-502.6.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23566	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23521	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00 ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23522	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00 ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23524	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23598	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23520	Path of Travel	Surface	\$1,840.00 ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23528	Path of Travel	Change in Level - Beveled	\$480.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23571	Path of Travel	Walking Surface Slope	\$3,600.00 ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23572	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23573	Path of Travel	Walking Surface Slope	\$3,600.00 ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/24	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23574	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/24	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23575	Path of Travel	Opening	\$185.00 ADA 302.3	Not_Started	12/31/24	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23577	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/28	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23586	Path of Travel	Surface	\$1,840.00 ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/28	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23587	Path of Travel	Walking Surface Slope	\$3,600.00 ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23588	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23590	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/28	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23591	Path of Travel	Crosswalk	\$1,100.00 ADA 406.5, 406.6, 705	Not_Started	12/31/28	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23589	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/28	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23597	Path of Travel	Surface	\$1,840.00 ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23600	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/22	3/16/21 \$432.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23601	Path of Travel	Crosswalk	\$1,100.00 ADA 406.5, 406.6, 705	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23599	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23613	Path of Travel	Opening	\$185.00 ADA 302.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23655	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23578	Stairs	Handrail Diameter	\$2,320.00 ADA 504.6, 505, 505.7.1, CA 11B-505.7	Not_Started	12/31/22	\$0.00

Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23579	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23580	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23581	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 118-505.10.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23582	Stairs	Handrail Diameter	\$2,320.00	ADA 504.6, 505, 505.7.1, CA 118-505.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23583	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23584	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 118-505.10.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23585	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 118-505.10.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23568	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23569	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23525	Doors	Pull Side Floor Surface Slope	\$1,040.00	ADA 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23526	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23570	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23523	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23592	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23510	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23537	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23642	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23656	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23513	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23514	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 118-604.5.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23511	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23530	Restrooms	Distance from front of the closet	\$277.00		Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23531	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23533	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23534	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23535	Restrooms	Urinal Rim Extension	\$951.00	ADA 605, 605.2, CA 118-605.2	Not_Set	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23532	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23536	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23576	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23604	Restrooms	Grab Bars	\$267.00	ADA 603, 604.5, 609, CA 118-604.5	Not_Started	12/31/22	\$0.00

Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23609	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23605	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23607	Restrooms	Toilet Flush Control - Wide Side	\$127.00 ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23608	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23617	Restrooms	Lavatory Control Type	\$392.00 ADA 213, 309.4, 606, CA 11B-213, 309.4, 606	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23618	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23619	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23620	Restrooms	Lavatory Pipes Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23621	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23622	Restrooms	Door Signage	\$158.00 CA 11B-216.8, 703.7.2.6	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23623	Restrooms	International Symbol of Accessibility	\$158.00 ADA 216, 216.8, 703, 703.7, CA 11B-703.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23624	Restrooms	Wall Signage Height	\$158.00 ADA 216, 703	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23614	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23615	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23616	Restrooms	Dispenser Operation	\$277.00 ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23625	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00 ADA 304, 305.1, 309.2, CA 11B-305.1, 309.2, 603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23626	Restrooms	Clear Space in Front of Compartment	\$4,000.00 ADA 603, 604.8.1.2, CA 11B-604.8.1.2, 604.8.2.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23627	Restrooms	Toilet Compartment Width	\$4,000.00 ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23628	Restrooms	Toilet Compartment Length	\$4,000.00 ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23629	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23630	Restrooms	Path of Travel width	\$2,400.00 ADA 213, 604, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23631	Restrooms	Grab Bars	\$267.00 ADA 603, 604.5, 609, CA 11B-604.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23636	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23637	Restrooms	Compartment Door Width	\$4,000.00 ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23638	Restrooms	Toilet Compartment Door	\$4,000.00 ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23639	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23640	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23641	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23632	Restrooms	Toilet Seat Height	\$1,707.00 ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23634	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/38	\$0.00

Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23635	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23651	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23646	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 118-213, 309.4, 606	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23647	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23648	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/38	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23649	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23650	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23652	Restrooms	Door Signage	\$158.00	CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23653	Restrooms	International Symbol of Accessibility	\$158.00	ADA 216, 216.8, 703, 703.7, CA 118-703.7	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23654	Restrooms	Wall Signage Height	\$158.00	ADA 216, 703	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23643	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23644	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 118-309.4, 603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23645	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23593	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23594	Drinking Fountains	Protruding Object	\$550.00	ADA 211, 305, 306, 307.2, 602, CA 118-307.2, 602	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23595	Drinking Fountains	Clear Floor Space Slope	\$2,200.00	ADA 211, 305, 305.2, 306, 602, CA 118-602.2	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23596	Drinking Fountains	Detectable Warnings	\$640.00	ADA 307.2, 602.1, CA 118-602.9	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23515	Food Service	Minimum Required Seating	\$2,500.00	ADA 206, 226.1, 305, CA 118-226.1	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23516	Food Service	Table Knee Depth	\$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, CA 118-306.3.2, 306.3.3, 902.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23517	Food Service	Counter is a Protruding Object	\$250.00	ADA 307.2, 902, CA 118-307.2	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23518	Food Service	Counter/Condiment/Tableware Height	\$2,500.00	ADA 902, 904.5, CA 118-904.4, 904.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23519	Food Service	Counter/Condiment/Tableware Height	\$2,500.00	ADA 902, 904.5, CA 118-904.4, 904.5	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23567	Emergency Warning Systems	Emergency Warning System	\$2,200.00	ADA 215, 702, CA 118-215, 702	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23527	Lockers	Accessible Lockers Availability	\$1,840.00	ADA 225.2.1, 811, CA 118-225.2.1, 811	Not_Started	12/31/22	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23610	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 118-305.2	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23611	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23612	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 118-305.2	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23602	Benches	On Accessible Route	\$1,840.00	ADA 205, 228, 305, 308, 309, 903	Not_Started	12/31/30	\$0.00
Dryden Park Golf Course - 902 S. Sunset Avenue Modesto, CA 95354	23603	Benches	Clear Floor Space	\$1,840.00	ADA 206, 305, 903.2, CA 118-206, 305, 903.2	Not_Started	12/31/30	\$0.00

James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31501	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 11B-502	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31502	Parking	Parking Lot Warning Sign	\$250.00 CA 11B-502.8	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31518	Parking	Vehicle Encroaches Into Path of Travel	\$250.00 ADA 502, 502.7, CA 11B-502.7.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31519	Parking	ISA is Faded or Damaged	\$117.00 ADA 502, CA 11B-502.6.4	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31488	Parking	Parking Space Width	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31489	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31490	Parking	Parking Space Length	\$350.00 CA 11B-502.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31491	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31492	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31493	Parking	Parking Space Width	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31494	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31495	Parking	Parking Space Length	\$350.00 CA 11B-502.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31496	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31498	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31520	Parking	Vehicle Encroaches Into Path of Travel	\$250.00 ADA 502, 502.7, CA 11B-502.7.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31521	Parking	ISA is Faded or Damaged	\$117.00 ADA 502, CA 11B-502.6.4	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31522	Parking	Access Aisle is Faded or Damaged	\$250.00 ADA 502.3, 502.3.3, CA 11B-502.3	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31523	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31504	Curb Ramps	Detectable Warnings	\$248.00 CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31505	Curb Ramps	Parallel Curb Ramp Right Side Cross Slope	\$1,300.00 ADA 405.3, 406.1, CA 11B-406.5.7	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31506	Curb Ramps	Top Landing Right Side Slope - Parallel Curb Ramp	\$1,260.00 ADA 403.3, 406.1, 406.4, CA 11B-406.5.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31507	Curb Ramps	Top Landing Right Side Clear Length - Parallel Curb Ramp	\$240.00 ADA 406.4, CA 11B-406.5.3, CA MUTCD	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31431	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31471	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00 ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31469	Path of Travel	Walking Surface Slope	\$3,600.00 ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31470	Path of Travel	Opening	\$185.00 ADA 302.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31458	Ramps	Landing Slope	\$2,872.00 ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31475	Stairs	Riser Striping	\$944.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00

James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31476	Stairs	Handrail Distance From Wall	\$1,916.00	ADA 504, 504.6, 505.5, CA 11B-505.5	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31477	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31478	Stairs	Handrail Smoothness	\$1,528.00	ADA 504.6, 505, 505.8, CA 11B-504.6, 505.8	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31479	Stairs	Handrail Smoothness	\$1,528.00	ADA 504.6, 505, 505.8, CA 11B-504.6, 505.8	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31429	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31435	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31437	Doors	Floor Mat	\$252.00	ADA 302.1, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/21	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31436	Doors	Door Opening Pressure	\$50.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31457	Doors	Door Opening Pressure	\$75.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31460	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31483	Doors	Door Opening Pressure	\$50.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31513	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/21	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31512	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31511	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31428	Counters	Counter Length	\$545.00	CA 11B-904.4	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31434	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31438	Signage	Information Signage	\$158.00	ADA 216.3, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31459	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31474	Signage	Accessible Element/Entrance Signage	\$316.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31480	Signage	Highest Tactile Character Height	\$632.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31481	Signage	Information Signage	\$158.00	ADA 216.3, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31482	Signage	Highest Tactile Character Height	\$158.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31524	Signage	Accessible Element/Entrance Signage	\$474.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31430	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31455	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31452	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31453	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 11B-609.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31454	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31456	Restrooms	Located Behind Front of Seat	\$230.00	ADA 604.7, CA 11B-604.7	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31449	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00

James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31451	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31467	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31464	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31465	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 11B-609.3	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31466	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31468	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31461	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31463	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31486	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31487	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31510	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31525	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31509	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31508	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31439	Drinking Fountains	Knee Clearance	\$2,500.00	ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31442	Break/Conference Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 11B-305, 306, 606.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31443	Break/Conference Room	Pipes Wrapping	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31444	Break/Conference Room	Clear Floor Space Length	\$900.00	ADA 205, 228, 308, 309	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31445	Break/Conference Room	Supply Lines	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31447	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31448	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31440	Break/Conference Room	Tables - Knee Depth	\$2,174.00	ADA 205, 228, 306.3.3, 308, 309, CA 11B-306.3.2, 306.3.3, 902.2	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31441	Break/Conference Room	Aisle Width between Tables		ADA 205, 228, 308, 309	Not_Started	12/31/26	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31446	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31484	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 11B-305.2	Not_Started	12/31/31	\$0.00
James Marshall Center - 420-A Chicago Avenue Modesto, CA 95351	31485	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22864	Parking	Parking Lot Warning Sign Visibility	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22865	Parking	Parking Lot Warning Sign Blanks	\$250.00	CA 11B-502.8.2	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22812	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22813	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22814	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22815	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22816	Parking	Access Aisle Width	\$250.00 ADA 208, 502.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22817	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22818	Parking	Access Aisle Striping	\$350.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22819	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22820	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22821	Parking	Must Travel Behind Parked Cars	\$1,100.00 ADA 502.3, CA 11B-502.7.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22822	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22823	Parking	Access Aisle Width	\$250.00 ADA 208, 502.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22824	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22825	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22826	Parking	Access Aisle Striping	\$350.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22827	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22828	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22829	Parking	Access Aisle Width	\$350.00 ADA 502, 502.3.1, CA 11B-502.3.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22830	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22831	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22832	Parking	Access Aisle Striping	\$350.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22833	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22834	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22835	Parking	Must Travel Behind Parked Cars	\$1,100.00 ADA 502.3, CA 11B-502.7.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22836	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22837	Parking	Access Aisle Width	\$350.00 ADA 502, 502.3.1, CA 11B-502.3.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22838	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22839	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22840	Parking	Access Aisle Striping	\$350.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22841	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22842	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22843	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22844	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22845	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22846	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22847	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22848	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22849	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22850	Parking	Access Aisle Width	\$350.00	ADA 502, 502.3.1, CA 11B-502.3.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22851	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22852	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22853	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22854	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22855	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22856	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22857	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22858	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22859	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22860	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22861	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22862	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22863	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22876	Parking	Required Minimum Van Accessible Spaces	\$1,611.00	ADA 208, 208.2.4, CA 11B-208.2.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22918	Parking	Parking Lot Warning Sign Visibility	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22919	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00	CA 11B-502	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22877	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22878	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22914	Parking	Parking Space Length	\$350.00 CA 11B-502.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22915	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22916	Parking	Parking Space Length	\$350.00 CA 11B-502.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22917	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22809	Curb Ramps	Detectable Warnings	\$248.00 CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22811	Curb Ramps	Right Side Flare Slope	\$1,300.00 ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22871	Curb Ramps	Detectable Warnings	\$248.00 CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22872	Curb Ramps	Curb Ramp Slope	\$1,300.00 ADA 405.2, 406, 406.1, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22873	Curb Ramps	Bottom Landing Slope	\$1,260.00 ADA 406, 406.2, CA 11B-406.5.8	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22874	Curb Ramps	Bottom Landing Change in Level - Curb Ramps	\$255.00 ADA 406.2, CA 11B-406.5.8	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22735	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22786	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22510	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22626	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00 ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22664	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22755	Path of Travel	Grating	\$1,088.00 ADA 302, 302.3	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22754	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22804	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22806	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22807	Path of Travel	Crosswalk	\$1,100.00 ADA 406.5, 406.6, 705	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22805	Path of Travel	Surface	\$1,840.00 ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22808	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22867	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22866	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22868	Path of Travel	Designated Accessible Route	\$1,840.00 ADA 206, 206.2, 402.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22869	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22870	Path of Travel	Crosswalk	\$1,100.00 ADA 406.5, 406.6, 705	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22875	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22920	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22532	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22503	Ramps	Ramp Run Slope	\$3,600.00	ADA 405, 405.2, CA 11B-405.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22504	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22505	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22506	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22507	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22508	Ramps	Ramp Run Slope	\$3,600.00	ADA 405, 405.2, CA 11B-405.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22534	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22535	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22536	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22537	Ramps	Handrail Extension	\$2,400.00	ADA 405, 405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22538	Ramps	Handrail Extension	\$2,400.00	ADA 405, 405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22556	Ramps	Landing Length	\$2,600.00	ADA 405.7, 405.7.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22557	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22564	Ramps	Handrail Extension	\$2,400.00	ADA 405, 405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22565	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22566	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22567	Ramps	Handrail Extension	\$2,400.00	ADA 405, 405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22568	Ramps	Handrail Extension Length	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22569	Ramps	Handrail Extension	\$2,400.00	ADA 405, 405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22570	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22571	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22572	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22573	Ramps	Is Handrail Extension Parallel	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22688	Elevators	Evacuation Signage	\$207.00	ADA 302, 407	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22689	Elevators	Re-opening Device	\$800.00	ADA 407, 407.3.3.2, CA 11B-407.3.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22690	Elevators	Door	\$800.00	ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22691	Elevators	Emergency System	\$4,500.00	ADA 309.4, 407, 407.4.6, CA 11B-309	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22692	Elevators	Emergency System	\$1,200.00	ADA 308, 407, 407.4.9, ASME A17.1, CA 11B-308, 407.4.9	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22693	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22694	Elevators	Jamb Marking	\$1,500.00	ADA 407, CA 11B-407.2.3.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22695	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22400	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22545	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22546	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22610	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22614	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22627	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22673	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22696	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22702	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22730	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22737	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22802	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22402	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22401	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22732	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22404	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22407	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22405	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22406	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22576	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22705	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22706	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22717	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22716	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22803	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22399	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22509	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22615	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22672	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22671	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22733	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22753	Doors	Door Opening Pressure	\$50.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22408	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22409	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22411	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22412	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22413	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22410	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22462	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22463	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22464	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22493	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22494	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22495	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22496	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22497	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22498	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22500	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22501	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22499	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22616	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22703	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22704	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22646	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22657	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22658	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/21	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22611	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22617	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22632	Signage	Accessible Element/Entrance Signage	\$158.00 ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22736	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22738	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22739	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22801	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22502	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22575	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22586	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22647	Signage	Accessible Element/Entrance Signage	\$158.00 ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22810	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22414	Signage	Room Identification	\$316.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22416	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22471	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22492	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22558	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22574	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22731	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22734	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22752	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22756	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22403	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22415	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22533	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22547	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22630	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22631	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22628	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22629	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22645	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22644	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22663	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22661	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 118-606.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22662	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22659	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22660	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22751	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22750	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22511	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22515	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22516	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22517	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22518	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22514	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22519	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22512	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22598	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22599	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22600	Restrooms	Wall Signage Height	\$158.00 ADA 216, 703	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22595	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22596	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22597	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22594	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22674	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22675	Restrooms	Seat Cover Dispenser	\$277.00 ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22686	Restrooms	Distance from front of the closet	\$277.00	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22682	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22683	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22684	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22685	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22679	Restrooms	Side Grab Bar Height	\$500.00 ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22680	Restrooms	Rear Grab Bar Interferes	\$231.00 ADA 609.3, CA 118-609.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22681	Restrooms	Rear Grab Bar Height	\$231.00 ADA 603, 609.4, CA 118-609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22687	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22676	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22678	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22765	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22766	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22767	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22768	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22764	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22633	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00 ADA 304, 305.1, 309.2, CA 118-305.1, 309.2, 603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22634	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22641	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22637	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22638	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22639	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22640	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22642	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22636	Restrooms	Toilet Clear Floor Space	\$3,500.00 ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22648	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00 ADA 304, 305.1, 309.2, CA 118-305.1, 309.2, 603.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22649	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22656	Restrooms	Distance from front of the closet	\$277.00	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22653	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22654	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22655	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22652	Restrooms	Side Grab Bar Height	\$500.00 ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22651	Restrooms	Toilet Clear Floor Space	\$3,500.00 ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22669	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22670	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22665	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22666	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22667	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22668	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22718	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22728	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22723	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22724	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22725	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22726	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22727	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22722	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22729	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22719	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22721	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22769	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22770	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22773	Restrooms	Distance from front of the closet	\$277.00		Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22774	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22771	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22787	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22788	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22799	Restrooms	Distance from front of the closet	\$277.00		Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22794	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22795	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22796	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22797	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22798	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22791	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22792	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 118-609.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22793	Restrooms	Rear Grab Bar Height	\$231.00	ADA 603, 609.4, CA 118-609.4	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22800	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22790	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22439	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22440	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22447	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22444	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22445	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22446	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22441	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22443	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22448	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22449	Restrooms	Toilet Compartment Length	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22450	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22451	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22456	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22457	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22458	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22459	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22455	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22460	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22453	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22454	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22469	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22466	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22467	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22468	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22470	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22465	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22484	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22485	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22479	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22480	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22481	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22482	Restrooms	Lavatory Clear Floor Space Length	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 118-305, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22483	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22478	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22544	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22542	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22543	Restrooms	Rear Grab Bar Height	\$231.00	ADA 603, 609, 609.4, CA 118-609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22539	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22541	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22582	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22583	Restrooms	Urinal Clear Floor Space Width	\$1,707.00	ADA 305.3, 605, 605.3, CA 118-305.3, 605.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22584	Restrooms	Restroom Urinal	\$2,300.00	ADA 305, 605, 605.3, CA 118-605.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22581	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22578	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22579	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22580	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22585	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22605	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22606	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22607	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22609	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22608	Restrooms	Unisex Restroom Signage	\$158.00	CA 118-703.7.2.6.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22604	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22775	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22776	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22780	Restrooms	Grab Bar Distance From Back Wall	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22781	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22782	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22777	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22779	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22525	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22526	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22527	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22528	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22529	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22523	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22524	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22548	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22549	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22550	Restrooms	Path of Travel width	\$2,400.00	ADA 213, 604, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22551	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22554	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22555	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22553	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22624	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22620	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22621	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22622	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22623	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22625	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22618	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22619	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22700	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22701	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22698	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22699	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22697	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22707	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22708	Restrooms	Seat Cover Dispenser	\$277.00 ADA 609.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22714	Restrooms	Distance from front of the closet	\$277.00	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22713	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22710	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22711	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22712	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22715	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22740	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22747	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22743	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22744	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22745	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22746	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22742	Restrooms	Rear Grab Bar Interferes	\$231.00 ADA 609.3, CA 11B-609.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22748	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22476	Drinking Fountains	Protruding Object	\$550.00 ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22477	Drinking Fountains	Spout Height for Standing Persons	ADA 602.7	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22577	Drinking Fountains	Fountain Type	\$2,500.00 ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22437	Drinking Fountains	Fountain Type	\$2,500.00 ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22438	Drinking Fountains	Protruding Object	\$550.00 ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22490	Drinking Fountains	Fountain Type	\$2,500.00 ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22491	Drinking Fountains	Spout Height	\$627.00 ADA 211, 602, 602.4, CA 11B-602.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22520	Drinking Fountains	Knee Clearance	\$2,500.00 ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22521	Drinking Fountains	Spout Height for Standing Persons	ADA 602.7	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22522	Drinking Fountains	Clear Floor Space Slope	\$2,200.00 ADA 211, 305, 305.2, 306, 602, CA 11B-602.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22530	Drinking Fountains	Knee Clearance	\$2,500.00 ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22531	Drinking Fountains	Spout Height for Standing Persons	ADA 602.7	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22601	Drinking Fountains	Fountain Type	\$2,500.00 ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22602	Drinking Fountains	Protruding Object	\$550.00 ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22603	Drinking Fountains	Stream Height	\$2,500.00 ADA 211, 602, 602.6, CA 11B-211, 602	Not_Started	12/31/31	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22559	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22560	Drinking Fountains	Protruding Object	\$550.00	ADA 211, 305, 306, 307.2, 602, CA 118-307.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22561	Drinking Fountains	Spout Height	\$627.00	ADA 211, 602, 602.4, CA 118-602.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22562	Drinking Fountains	Stream Trajectory	\$2,875.00	ADA 602.6, CA 118-602.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22563	Drinking Fountains	Fountain Depth	\$2,500.00	ADA 211, 305, 306, 602, CA 118-602.8	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22757	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22758	Drinking Fountains	Protruding Object	\$550.00	ADA 211, 305, 306, 307.2, 602, CA 118-307.2, 602	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22759	Drinking Fountains	Spout Height	\$627.00	ADA 211, 602, 602.4, CA 118-602.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22420	Outdoor Sports Areas	Semi Ambulatory Seats - Clear Leg Space	\$505.00		Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22421	Outdoor Sports Areas	Total Semi Ambulatory Seats	\$600.00	ADA 221.4, CA 118-221.4, 221.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22430	Outdoor Sports Areas	Ticket Booth Counter Height	\$329.00	ADA 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22431	Outdoor Sports Areas	Counter Length	\$329.00	ADA 904	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22432	Outdoor Sports Areas	Counter Length	\$329.00	ADA 904	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22433	Outdoor Sports Areas	Ticket Booth Counter Height	\$329.00	ADA 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22434	Outdoor Sports Areas	Counter Length	\$329.00	ADA 904	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22435	Outdoor Sports Areas	Counter Length	\$329.00	ADA 904	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22436	Outdoor Sports Areas	Counter Length	\$329.00	ADA 904	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22422	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22423	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22424	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22425	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22426	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22427	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22428	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22429	Outdoor Sports Areas	Edge Protection	\$2,200.00	ADA 225, 802	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22587	Locker Rooms	Accessible Benches	\$500.00	ADA 222, 803, 803.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22461	Locker Rooms	Accessible Benches	\$500.00	ADA 222, 803, 803.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22612	Play Area	Transfer Platform	\$3,360.00	ADA 1008, 1008.3.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22613	Play Area	Clear Floor Space Centered/Parallel	\$1,840.00	ADA 1008.3.1.3, 305.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22783	Break/Conference Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 118-305, 306, 606.2	Not_Started	12/31/26	\$0.00

John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22784	Break/Conference Room	Pipes Wrapping	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22785	Break/Conference Room	Supply Lines	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22760	Sinks	Pipes Wrapping	\$447.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22761	Sinks	Supply Lines	\$447.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22762	Sinks	Sink	\$540.00	ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22763	Sinks	Sink	\$540.00	ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22417	Accessible Showers	Width	\$3,500.00	ADA 608, 608.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22418	Accessible Showers	Seat	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22419	Accessible Showers	Twist Control on Hand held Mount	\$540.00	ADA 213, 608, 608.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22473	Accessible Showers	Seat Length	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22474	Accessible Showers	Seat Distance From Wall	\$1,500.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22475	Accessible Showers	Soap Dish Location	\$277.00	CA 11B-608.10	Not_Started	12/31/26	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22472	Accessible Showers	Hand Held Unit	\$385.00	ADA 213, 608, CA 11B-608.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22486	Accessible Showers	Width	\$3,500.00	ADA 608, 608.2	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22487	Accessible Showers	Accessible Shower	\$1,840.00	ADA 608.2.1	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22488	Accessible Showers	Seat	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22489	Accessible Showers	Twist Control on Hand held Mount	\$540.00	ADA 213, 608, 608.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22591	Accessible Showers	Seat Distance From Wall	\$1,500.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22592	Accessible Showers	Seat Height	\$1,500.00	ADA 608, 610.3, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22589	Accessible Showers	Grab Bar Height	\$78.00	ADA 608, CA 11B-608.3, 609.4	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22590	Accessible Showers	Grab Bar is over Seat	\$1,840.00	ADA 608, 608.6, CA 11B-608.3, 609	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22588	Accessible Showers	Hand Held Unit	\$385.00	ADA 213, 608, CA 11B-608.6	Not_Started	12/31/31	\$0.00
John Thurman Ball Park - 601 Neece Drive Modesto, CA 95351	22593	Accessible Showers	Water Valve Height	\$554.00	ADA 213, 608, 608.5, CA 11B-608.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30670	Parking	Less Than Minimum Required Parking Spaces	\$370.00	ADA 208, 208.2, CA 11B-208.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30685	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30686	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00	CA 11B-502	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30687	Parking	Warning Signage	\$110.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30672	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30673	Parking	Parking Space	\$300.00	ADA 502, CA 11B-502	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30674	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30677	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30678	Parking	Parking Space Vertical Clearance	\$108.00	ADA 502, 502.5	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30679	Parking	Parking Space	\$300.00	ADA 502, CA 11B-502	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30680	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30682	Parking	Access Aisle Width	\$250.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30683	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30831	Curb Ramps	Projects into Traffic	\$1,400.00	ADA 406, 406.4, 406.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30832	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30833	Curb Ramps	Bottom Landing Change in Level	\$255.00	ADA 406.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30834	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30691	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30706	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30704	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30705	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30762	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30763	Path of Travel	Change in Level	\$600.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30783	Path of Travel	Change in Level	\$450.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30805	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30708	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30729	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30806	Platform Lifts	Light in Car	\$800.00	ADA 302, 410, ASME A18.1	Not_Started	12/31/26	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30807	Platform Lifts	Stand By Power	\$1,100.00	ADA 302, 410, ASME A18.1 , CA 118-207.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30809	Platform Lifts	Lowering device	\$300.00	ADA 302, 410, ASME A18.1	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30810	Platform Lifts	Platform Lifts	\$158.00	ADA 302, 410, ASME A18.1	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30811	Platform Lifts	Landing Change in Level	\$1,840.00	ADA 302, 410, ASME A18.1 , CA 118-303.2, 303.3, 410.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30812	Platform Lifts	Door Width		ADA 410.6, CA 118-410.6	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30813	Platform Lifts	Landing Slope	\$1,840.00	ADA 302, 410, ASME A18.1 , CA 118-305.2, 404.2.4.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30722	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 118-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30723	Stairs	Riser Striping	\$1,000.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30724	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30725	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 118-505.10.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30726	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 118-505.10.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30727	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30728	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6 , 505.10.3, CA 118-505.10.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30766	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 118-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30767	Stairs	Risers Striping Distance From Nosing	\$460.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30768	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 118-504.4.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30769	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30770	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.3, CA 118-505.10.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30771	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6 , 505.4, CA 118-504.6, 505	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30772	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, CA 118-505.10.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30773	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6 , 505.10.3, CA 118-505.10.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30665	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30666	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30669	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30668	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30667	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30696	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30697	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30707	Doors	Doorway Opening Width	\$3,600.00	ADA 404, 404.2.4.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30710	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30713	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30711	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30712	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30714	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30716	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30715	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30717	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30718	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30720	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30721	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30732	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30734	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30735	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30733	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30775	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30780	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30781	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30779	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30776	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30777	Doors	Door Hardware	\$50.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30778	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30784	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30785	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30786	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30787	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30798	Doors	Door Closer Vertical Clearance	\$250.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30799	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30800	Doors	Door Hardware	\$50.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30801	Doors	Door Closer Vertical Clearance	\$250.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30802	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30804	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30803	Doors	Door Hardware	\$50.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30730	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 11B-904.4	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30731	Counters	Protruding Object	\$450.00 ADA 307.2, 902	Not_Started	12/31/21	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30688	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30689	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30690	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30703	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30709	Signage	Room Identification	\$316.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30719	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30743	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30753	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30754	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30764	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30765	Signage	Accessible Element/Entrance Signage	\$474.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30782	Signage	Room Identification	\$316.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30835	Signage	Accessible Element/Entrance Signage	\$316.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30736	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30741	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30739	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 118-604.5, 609.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30740	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30742	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30737	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30747	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30751	Restrooms	Grab Bar Distance From Back Wall	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30752	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30748	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30750	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30760	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30759	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30761	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30755	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30756	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30757	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30758	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30788	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00	ADA 213, 213.2.1, CA 118-213.2.1	Not_Started	12/31/26	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30789	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00 ADA 304, 305.3, 603.2, 603.2.3, CA 118-603.2.3	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30796	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30797	Restrooms	Unisex Restroom Signage	\$158.00 CA 118-703.7.2.6.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30791	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30792	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30793	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 118-606.6	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30794	Restrooms	Lavatory Pipes Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30795	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30790	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30817	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30818	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30815	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30816	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30814	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30819	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30827	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30823	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30824	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00 CA 118-604.5.1	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30825	Restrooms	Rear Grab Bar Interferes	\$231.00 ADA 609.3, CA 118-609.3	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30826	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30828	Restrooms	Toilet Paper Dispenser Height	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30829	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30830	Restrooms	Distance to center of roll from floor	\$152.00 ADA 304, 604.7, CA 118-604.7	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30820	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00

King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30822	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30692	Drinking Fountains	Fountain Type	\$2,500.00 ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30693	Drinking Fountains	Protruding Object	\$550.00 ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30694	Drinking Fountains	Spout Height	\$627.00 ADA 211, 602, 602.4, CA 11B-602.4	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30695	Drinking Fountains	Detectable Warnings	\$640.00 ADA 307.2, 602.1, CA 11B-602.9	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30744	Drinking Fountains	Protruding Object	\$550.00 ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30745	Drinking Fountains	Stream Trajectory	\$2,875.00 ADA 602.6, CA 11B-602.6	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30746	Drinking Fountains	Detectable Warnings	\$640.00 ADA 307.2, 602.1, CA 11B-602.9	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30774	Emergency Warning Systems	Emergency Warning Systems	\$2,200.00 ADA 215, 702, CA 11B-215, 702	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30698	Sinks	Sink - Knee Clearance	\$1,800.00 ADA 205, 228, 308, 309, 606, CA 11B-306.3, 606.2	Not_Started	12/31/31	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30699	Sinks	Pipes Wrapping	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30700	Sinks	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30701	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
King Kennedy Center - 601 S Martin Luther King Drive Modesto, CA 95351	30702	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31394	Parking	Vehicles Encroach Into Path of Travel	\$240.00 ADA 502, 502.7, CA 11B-502.7.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31405	Parking	Parking Lot Warning Sign	\$250.00 CA 11B-502.8	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31395	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31396	Parking	Vehicle Encroaches Into Path of Travel	\$250.00 ADA 502, 502.7, CA 11B-502.7.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31397	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31398	Parking	ISA is Faded or Damaged	\$117.00 ADA 502, CA 11B-502.6.4	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31399	Parking	Van Accessible Signage	\$250.00 ADA 502, 502.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31400	Parking	Access Aisle Width	\$250.00 CA 11B-502.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31401	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31402	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31403	Parking	Access Aisle Striping	\$350.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31404	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31359	Curb Ramps	Curb Ramp Slope	\$1,300.00 ADA 405.2, 406, 406.1, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31360	Curb Ramps	Right Side Flare Slope	\$1,300.00 ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00

Maddux Center - 615 Sierra Drive Modesto, CA 95351	31361	Curb Ramps	Detectable Warnings Depth	\$190.00	ADA 705.1.2.2, CA 11B-705.1.2.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31362	Curb Ramps	Bottom Landing Slope	\$1,260.00	ADA 406, 406.2, CA 11B-406.5.8	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31314	Path of Travel	Change in Level	\$300.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31358	Path of Travel	Protruding Objects - Vertical Clearance	\$216.00	ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/21	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31357	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31301	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31300	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31302	Doors	Door Opening Pressure	\$50.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31318	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31319	Doors	Door Opening Pressure	\$100.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31325	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31326	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31324	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31340	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31339	Doors	Door Threshold	\$257.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31337	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31344	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31342	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31343	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31346	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31345	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31349	Doors	Front Approach Latch Side Clearance	\$11,684.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31348	Doors	Door Opening Pressure	\$100.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31351	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/21	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31350	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31356	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31388	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31387	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31391	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31390	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31392	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31417	Doors	Door Opening Pressure	\$175.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31418	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31420	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/21	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31419	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31323	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00

Maddux Center - 615 Sierra Drive Modesto, CA 95351	31303	Signage	Room Identification	\$790.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31341	Signage	Room Identification	\$790.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31363	Signage	Room Identification	\$948.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31386	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31393	Signage	Room Identification	\$948.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31422	Signage	Room Identification	\$474.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31364	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31308	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31309	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31305	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31306	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 118-604.4	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31311	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 118-604.5, 609.3	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31312	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31313	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31321	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 118-604.5, 609.3	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31322	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31335	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31328	Restrooms	Lavatory Type	\$420.00	ADA 213, 606, 606.2, CA 118-305, 306, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31329	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31330	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31331	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31332	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 118-305, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31333	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31334	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31327	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31353	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 118-604.5, 609.3	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31354	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31355	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31370	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31371	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31367	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31369	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31365	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00

Maddux Center - 615 Sierra Drive Modesto, CA 95351	31366	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31377	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31378	Restrooms	Toilet Compartment Door	\$4,000.00 ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31376	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31379	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31372	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31374	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31375	Restrooms	Toilet Clear Floor Space	\$3,500.00 ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31385	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31384	Restrooms	Door Signage	\$158.00 CA 11B-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31382	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 11B-606.6	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31383	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31380	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31381	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31406	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00 ADA 304, 305.3, 603.2, 603.2.3, CA 11B-603.2.3	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31407	Restrooms	Fixture Clear Floor Space	\$2,400.00 ADA 603.2.3, CA 11B-603.2.3	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31416	Restrooms	Door Signage Height	\$158.00 CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31409	Restrooms	Lavatory Type	\$420.00 ADA 213, 606, 606.2, CA 11B-305, 306, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31410	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31411	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31412	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 11B-606.6	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31413	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00 ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31414	Restrooms	Lavatory Pipes Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31415	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31408	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31304	Drinking Fountains	Knee Clearance	\$2,500.00 ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31389	Emergency Warning Systems	Emergency Warning Systems	\$2,200.00 ADA 215, 702, CA 11B-215, 702	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31316	Break/Conference Room	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31317	Break/Conference Room	Break Room	\$110.00 ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31315	Break/Conference Room	Tables - Knee Depth	\$2,174.00 ADA 205, 228, 306.3.3, 308, 309, CA 11B-306.3.2, 306.3.3, 902.2	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31336	Break/Conference Room	Control Height	ADA 308	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31423	Break/Conference Room	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31426	Break/Conference Room	Break Room	\$110.00 ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31427	Break/Conference Room	Break Room	\$110.00 ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31424	Break/Conference Room	Reach Height	\$1,200.00 ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31425	Break/Conference Room	Reach Height	\$1,200.00 ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	12/31/31	\$0.00
Maddux Center - 615 Sierra Drive Modesto, CA 95351	31421	Reach Ranges	Clear Floor Space Width	\$500.00 ADA 304, 305.3, CA 11B-305	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30489	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 11B-502	Not_Started	12/31/26	\$0.00

McHenry Mansion - 906 15th Street Modesto, CA 95354	30475	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30476	Parking	Parking Space Width	\$350.00 ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30477	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30478	Parking	Parking Space Length	\$350.00 CA 11B-502.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30479	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30480	Parking	Parking Space ISA Visibility	\$220.00 CA 11B-502.6.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30481	Parking	Parking Space Accessible Signage Height	\$158.00 ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30482	Parking	Van Accessible Signage	\$250.00 ADA 502, 502.6	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30483	Parking	Access Aisle Width	\$250.00 CA 11B-502.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30485	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30486	Parking	Access Aisle is Faded or Damaged	\$250.00 ADA 502.3, 502.3.3, CA 11B-502.3	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30487	Parking	Access Aisle	\$180.00 CA 11B-502.3.4	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30488	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30600	Curb Ramps	Detectable Warnings	\$248.00 CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30601	Curb Ramps	Left Side Flare Slope	\$1,300.00 ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30602	Curb Ramps	Bottom Landing Slope	\$1,260.00 ADA 406, 406.2, CA 11B-406.5.8	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30603	Curb Ramps	Bottom Landing Change in Level	\$255.00 ADA 406.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30473	Path of Travel	Protruding Objects - Vertical Clearance	\$432.00 ADA 307, 307.4, CA 11B-307.4	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30472	Path of Travel	Opening	\$185.00 ADA 302.3	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30492	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00 ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30490	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30491	Path of Travel	Change in Level	\$1,650.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30530	Path of Travel	Detectable Warnings	\$144.00 ADA 705, CA 11B-247.1.2.5	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30546	Path of Travel	Stairs or Steps Obstruction	\$3,500.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30547	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30427	Elevators	Evacuation Signage	\$207.00 ADA 302, 407	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30430	Elevators	Emergency System	ADA 407.4.9, ASME A17.1, CA 11B-407.4.9	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	31514	Elevators	Emergency System	\$800.00 ADA 407, 407.4.9, 708.2, CA 11B-407.4.9	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30436	Elevators	Door	\$800.00 ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30440	Elevators	Door	\$800.00 ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30432	Elevators	Control Button, Main Floor Indication	\$800.00 ADA 407, 407.4.7.1.3, CA 11B-407.4.7.1.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	31515	Elevators	Jamb Marking	ADA 407	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	31516	Elevators	Jamb Marking	ADA 407	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	31517	Elevators	Jamb Marking	ADA 407	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30464	Stairs	Handrail on One Side	\$1,528.00 ADA 504, CA 11B-504.6, 505.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30465	Stairs	Risers Height	\$8,520.00 ADA 504, CA 11B-504.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30466	Stairs	Riser Striping	\$944.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30467	Stairs	Handrail Extension Length	\$800.00 ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30468	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00

McHenry Mansion - 906 15th Street Modesto, CA 95354	30423	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30424	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30426	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30425	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30462	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30463	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30531	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30532	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30538	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30536	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30537	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30533	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30534	Doors	Bottom Door Panel Height	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30535	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30566	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30567	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30569	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30568	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30613	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30615	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30614	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30626	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30630	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30629	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30628	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30627	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30645	Doors	Door Opening Width	\$3,500.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30646	Doors	Door Opening Height	\$4,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30647	Doors	Accessible Hardware	\$1,600.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30648	Doors	Door Hardware	\$100.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30417	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30422	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30418	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30419	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30420	Doors	Bottom Door Panel Height	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30421	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Selected	12/31/26	\$0.00

McHenry Mansion - 906 15th Street Modesto, CA 95354	30550	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 118-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30556	Doors	Floor Mat	\$126.00 ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30555	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 118-404.2.5	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30551	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30552	Doors	Height	\$280.00 ADA 404, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30553	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30554	Doors	Bottom Door Panel	\$2,000.00 ADA 404, 404.2.10, CA 118-404.2.10	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30604	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30610	Doors	Front Approach Clear Floor Space Length	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	In_Progress	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30611	Doors	Floor Surface Slope	\$1,500.00 ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30612	Doors	Floor Mat	\$126.00 ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30609	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30608	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30605	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30606	Doors	Height	\$280.00 ADA 404, 404.2.7, CA 118-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30607	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30616	Doors	Doorway Opening Width	\$5,400.00 ADA 404, 404.2.4.2	Not_Selected	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30474	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30549	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30557	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30446	Restrooms	Toilet Compartment Width	\$4,000.00 ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30447	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30448	Restrooms	Seat Cover Dispenser	\$277.00 ADA 609.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30460	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30457	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30458	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30459	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30453	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30454	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00 CA 118-604.5.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30455	Restrooms	Rear Grab Bar Interferes	\$231.00 ADA 609.3, CA 118-609.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30456	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30461	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30449	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30450	Restrooms	Toilet Seat Height	\$1,707.00 ADA 603, 604.4, CA 118-604.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30452	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30576	Restrooms	Urinal Rim Height	\$1,397.00 ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30577	Restrooms	Urinal Flush Control Height	\$227.00 ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30578	Restrooms	Width Between Urinal Shields	\$1,800.00 ADA 305.7, 605, 605.3, CA 118-305.7, 605.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30575	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/31	\$0.00

McHenry Mansion - 906 15th Street Modesto, CA 95354	30579	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30580	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30572	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30573	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30574	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30570	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30571	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30581	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30582	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30583	Restrooms	Seat Cover Dispenser	\$277.00	ADA 609.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30597	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30591	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30592	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30593	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30594	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30595	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30596	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30589	Restrooms	Rear Grab Bar Interferes	\$231.00	ADA 609.3, CA 11B-609.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30590	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30598	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30584	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30585	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30587	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30588	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30599	Emergency Warning Systems	Emergency Warning System	\$2,200.00	ADA 215, 702, CA 11B-215, 702	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30558	Break/Conference Room	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 11B-606.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30559	Break/Conference Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 11B-305, 306, 606.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30560	Break/Conference Room	Pipes Wrapping	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30561	Break/Conference Room	Cabinet Door Hardware	\$1,000.00	ADA 205, 228, 308, 309, CA 11B-606.4	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30562	Break/Conference Room	Supply Lines	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30564	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	12/31/21	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30563	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	12/31/26	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30649	Sinks	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 11B-606.3	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30650	Sinks	Sink - Knee Clearance	\$1,800.00	ADA 205, 228, 308, 309, 606, CA 11B-306.3, 606.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30651	Sinks	Pipes Wrapping	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30652	Sinks	Toe Kick	\$420.00	ADA 305, 306, 606.2, CA 11B-305, 306, 606.2	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30653	Sinks	Clear Floor Space Width	\$900.00	ADA 205, 228, 308, 309	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30654	Sinks	Supply Lines	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30655	Sinks	Sink	\$180.00	ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00

McHenry Mansion - 906 15th Street Modesto, CA 95354	30443	Reach Ranges	Clear Floor Space Slope	\$500.00 ADA 304, CA 11B-305.2	Not_Started	12/31/40	\$0.00
McHenry Mansion - 906 15th Street Modesto, CA 95354	30548	Benches	Clear Floor Space Slope	\$1,840.00 ADA 305, 903.2, CA 11B-903.2	Not_Started	12/31/40	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20233	Parking	Required Minimum Van Accessible Spaces	\$370.00 ADA 208, 208.2.4, 502.7, CA 11B-208.2.4, 502.7	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20234	Parking	Parking Lot Warning Sign	\$250.00 CA 11B-502.8	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20235	Parking	Parking Lot Warnings	\$300.00 CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20237	Parking	Access Aisle - "No Parking"	\$250.00 CA 11B-502.3.3	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20032	Path of Travel	Walking Surface Slope	\$3,600.00 ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20198	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20199	Path of Travel	Crosswalk Striping	\$300.00 ADA 705	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20218	Path of Travel	Change in Level	\$150.00 ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20221	Path of Travel	Crosswalks and Detectable Warnings	\$190.00 ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20222	Path of Travel	Crosswalk	\$1,100.00 ADA 406.5, 406.6, 705	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20219	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20220	Path of Travel	Curb is on The Path of Travel	\$2,500.00 ADA 206, 302, 303, 303.4, 402, 403.4, 406	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20261	Path of Travel	Walking Surface Cross Slope	\$3,600.00 ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20020	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00 ADA 307, 307.4, CA 11B-307.4	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20102	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00 ADA 307, 307.4, CA 11B-307.4	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20181	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00 ADA 307, 307.2, CA 11B-307.2	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20031	Path of Travel	Mat or Runner	\$42.00 ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20173	Elevators	Evacuation Signage	\$207.00 ADA 302, 407	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20174	Elevators	Door	\$800.00 ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20175	Elevators	Emergency System	\$1,200.00 ADA 308, 407, 407.4.9, ASME A17.1, CA 11B-308, 407.4.9	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20063	Stairs	Middle Handrail	\$1,528.00	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20064	Stairs	Riser Nosing Smoothness	\$1,432.00 ADA 504, 504.5, CA 11B-504.5	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20065	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20066	Stairs	Handrail Extension	\$1,916.00 ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20067	Stairs	Is Handrail Extension Parallel	\$627.00 ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20068	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20069	Stairs	Handrail Extension	\$1,916.00 ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20070	Stairs	Is Handrail Extension Parallel	\$627.00 ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20071	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20072	Stairs	Middle Handrail	\$1,528.00	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20073	Stairs	Riser Nosing Smoothness	\$1,432.00 ADA 504, 504.5, CA 11B-504.5	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20074	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20075	Stairs	Handrail Extension	\$1,916.00 ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20076	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20077	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20078	Stairs	Handrail Extension	\$1,916.00 ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00

McHenry Museum - 1402 I Street	Modesto, CA 95354	20207	Stairs	Is Handrail Extension Parallel	\$800.00 ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20208	Stairs	Is Handrail Extension Parallel	\$627.00 ADA 504, CA 11B-505.10.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20209	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20033	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20034	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20038	Doors	Front Approach Clear Floor Space Length	\$2,921.00 ADA 404, 404.2.4, CA 11B-404.2.4	In_Progress	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20037	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20035	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20036	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20081	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20082	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20084	Doors	Front Approach Clear Floor Space Length	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20085	Doors	Front Approach Clear Floor Space Length	\$2,921.00 ADA 404, 404.2.4, CA 11B-404.2.4	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20083	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20210	Doors	Door Closer Vertical Clearance	\$250.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20211	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20212	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20215	Doors	Front Approach Clear Floor Space Length	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20216	Doors	Front Approach Clear Floor Space Length	\$2,921.00 ADA 404, 404.2.4, CA 11B-404.2.4	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20214	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20213	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20239	Doors	Door Opening Width	\$1,750.00 ADA 404, 404.2.3, CA 11B-404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20240	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20241	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20262	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20263	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/40	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20151	Doors	Floor Surface Slope	\$1,500.00 ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20149	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20150	Doors	Bottom Door Panel	\$2,000.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20169	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20170	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20172	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/40	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20171	Doors	Bottom Door Panel Height	\$2,000.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20176	Doors	Door Opening Height	\$2,000.00 ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20178	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/40	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20177	Doors	Bottom Door Panel Height	\$2,000.00 ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20061	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20160	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	In_Progress	12/31/26	\$0.00
McHenry Museum - 1402 I Street	Modesto, CA 95354	20231	Signage	Room Identification	\$158.00 ADA 216, 216.2, 703, CA 11B-216.2	In_Progress	12/31/26	\$0.00

McHenry Museum - 1402 I Street Modesto, CA 95354	20039	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20217	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20232	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20021	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00	ADA 304, 305.1, 309.2, CA 11B-305.1, 309.2, 603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20022	Restrooms	Toilet Paper Dispenser	\$277.00	ADA 603, 604.7, CA 11B-604.7	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20023	Restrooms	Side Grab Bar	\$267.00	ADA 603, 604.5, 604.8.1.5, CA 11B-604.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20024	Restrooms	Back Wall Grab Bar	\$267.00	ADA 603, 604.5, 604.8.1.5, CA 11B-604.5, 604.8.1.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20025	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20030	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20026	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20028	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20029	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20086	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00	ADA 304, 305.1, 309.2, CA 11B-305.1, 309.2, 603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20087	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20088	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20089	Restrooms	Grab Bars	\$267.00	ADA 603, 604.5, 609, CA 11B-604.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20100	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20095	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20096	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20097	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20098	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20099	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20101	Restrooms	Located Behind Front of Seat	\$230.00	ADA 604.7, CA 11B-604.7	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20090	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20091	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20093	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20094	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20103	Restrooms	Circular Turning Space Diameter	\$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 11B-304.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20112	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20106	Restrooms	Lavatory Type	\$420.00	ADA 213, 606, 606.2, CA 11B-305, 306, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20107	Restrooms	Lavatory Surface Height	\$1,286.00	ADA 213, 606, 606.3, CA 11B-213, 606.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20108	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20109	Restrooms	Lavatory Clear Floor Space Length	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20110	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20111	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20114	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20113	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/31	\$0.00

McHenry Museum - 1402 I Street	20104	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20105	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20182	Restrooms	Accessible Route	\$1,840.00	ADA 206.2.2, 213, 603, CA 11B-213.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20183	Restrooms	Circular Turning Space Diameter	\$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 11B-304.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20194	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20195	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 11B-605.4	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20192	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20193	Restrooms	Mirror Top Height	\$250.00	ADA 213, 603, 603.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20186	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 11B-213, 309.4, 606	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20187	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20188	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20189	Restrooms	Lavatory Clear Floor Space Length	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20190	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20191	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20196	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street	20197	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
McHenry Museum - 1402 I Street	20184	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20185	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20242	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20243	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20244	Restrooms	Path of Travel width	\$2,400.00	ADA 213, 604, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20245	Restrooms	Grab Bars	\$267.00	ADA 603, 604.5, 609, CA 11B-604.5	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20259	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20251	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20252	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20253	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20254	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20255	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20256	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20257	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20258	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20260	Restrooms	Located Behind Front of Seat	\$230.00	ADA 604.7, CA 11B-604.7	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20246	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20247	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20249	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20250	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20152	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20153	Drinking Fountains	Knee Clearance	\$2,500.00	ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street	20154	Drinking Fountains	Stream Trajectory	\$2,875.00	ADA 602.6, CA 11B-602.6	Not_Started	12/31/31	\$0.00

McHenry Museum - 1402 I Street Modesto, CA 95354	20155	Drinking Fountains	Detectable Warnings	\$640.00 ADA 307.2, 602.1, CA 118-602.9	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20179	Assembly Areas	Access to Performing Area	\$8,210.00 ADA 206, 221, 802, CA 118-206.2.6	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20180	Assembly Areas	Wheelchair Location	\$1,840.00 ADA 225, 802	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20062	Emergency Warning Systems	Emergency Warning Systems	\$2,200.00 ADA 215, 702, CA 118-215, 702	Not_Started	12/31/31	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20156	Sinks	Sink - Counter Height	\$1,800.00 ADA 606.3, CA 118-606.3	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20157	Sinks	Pipes Wrapping	\$149.00 ADA 606.5, CA 118-606.5	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20158	Sinks	Toe Kick	\$420.00 ADA 305, 306, 606.2, CA 118-305, 306, 606.2	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20159	Sinks	Supply Lines	\$149.00 ADA 606.5, CA 118-606.5	Not_Selected	12/31/26	\$0.00
McHenry Museum - 1402 I Street Modesto, CA 95354	20238	Reach Ranges	Clear Floor Space Slope	\$500.00 ADA 304, CA 118-305.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31106	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 118-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31107	Parking	Warning Signage	\$110.00 CA 118-502.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31108	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 118-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31109	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 118-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31110	Parking	Warning Signage	\$110.00 CA 118-502.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31111	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00 CA 118-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31052	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31053	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 118-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31054	Parking	Accessible Signage	\$250.00 ADA 502, 502.6, 703.7.2.1, CA 118-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31055	Parking	Parking Space Length	\$350.00 CA 118-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31056	Parking	Parking Lot Warnings	\$300.00 CA 118-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31058	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 118-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31059	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31060	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 118-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31061	Parking	Accessible Signage	\$250.00 ADA 502, 502.6, 703.7.2.1, CA 118-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31062	Parking	Parking Lot Warnings	\$300.00 CA 118-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31063	Parking	Access Aisle Slope	\$3,800.00 ADA 502, 502.4, CA 118-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31064	Parking	Outline is Faded, Damaged or Missing	\$350.00 ADA 502, 502.2, CA 118-502.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31065	Parking	Parking Space Slope	\$3,800.00 ADA 502, 502.4, CA 118-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31066	Parking	Accessible Signage	\$250.00 ADA 502, 502.6, 703.7.2.1, CA 118-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31067	Parking	Parking Space Length	\$350.00 CA 118-502.2	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31068	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31070	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31071	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31072	Parking	Vehicle Encroaches Into Path of Travel	\$250.00	ADA 502, 502.7, CA 11B-502.7.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31073	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31074	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31075	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31076	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31077	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31078	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31079	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31080	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31082	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31083	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31084	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31085	Parking	Parking Space	\$300.00	ADA 502, CA 11B-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31086	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31087	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31088	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31089	Parking	Access Aisle Width	\$350.00	ADA 502, 502.3.1, CA 11B-502.3.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31091	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31092	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31093	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31094	Parking	Parking Space	\$300.00	ADA 502, CA 11B-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31095	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31096	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31097	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31099	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31100	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31101	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31102	Parking	Parking Space	\$300.00	ADA 502, CA 11B-502	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31103	Parking	Parking Space Length	\$350.00	CA 11B-502.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31104	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31105	Parking	Parking Space Accessible Signage Height	\$158.00	ADA 502, 502.6, CA 11B-502.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31046	Passenger Loading Zones	Access Aisle	\$650.00	ADA 502, 503, 503.3, CA 11B-503.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31047	Passenger Loading Zones	Sign	\$220.00	ADA 503.3.3, CA 11B-503.6, 703.5, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31232	Passenger Loading Zones	Curbs Between Access Aisle and Vehicle Pull-up Space	\$150.00	ADA 502, 503, 503.4, CA 11B-206.2.1, 303.4, 503.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31233	Passenger Loading Zones	Access Aisle	\$650.00	ADA 502, 503, 503.3, CA 11B-503.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31234	Passenger Loading Zones	Sign	\$220.00	ADA 503.3.3, CA 11B-503.6, 703.5, 703.7.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30903	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30904	Curb Ramps	Parallel Curb Ramp Left Side Slope	\$1,300.00	ADA 405.2, 406.1, CA 11B-406	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30905	Curb Ramps	Bottom Landing Slope	\$240.00	ADA 402, 403.3, 406.1, 406.2, 406.4, CA 11B-406.3.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30906	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30907	Curb Ramps	Top Landing Right Side Slope - Parallel Curb Ramp	\$1,260.00	ADA 403.3, 406.1, 406.4, CA 11B-406.5.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30951	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30952	Curb Ramps	Curb Ramp Slope	\$1,300.00	ADA 405.2, 406, 406.1, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30953	Curb Ramps	Left Side Flare Slope	\$1,300.00	ADA 406.3, CA 11B-406.2.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30954	Curb Ramps	Bottom Landing Slope	\$240.00	ADA 402, 403.3, 406.1, 406.2, 406.4, CA 11B-406.3.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30955	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31278	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31279	Curb Ramps	Curb Ramp - Cross Slope	\$1,300.00	ADA 402, 405.3, 406.1, CA 11B-406.5.7	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31280	Curb Ramps	Bottom Landing Slope	\$240.00	ADA 402, 403.3, 406.1, 406.2, 406.4, CA 11B-406.3.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31281	Curb Ramps	Bottom Landing Change in Level	\$255.00	ADA 406.2	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31282	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30865	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30866	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30873	Path of Travel	Grating	\$2,176.00	ADA 302, 302.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30911	Path of Travel	Drop Off Hazard	\$1,088.00	ADA 303.5, CA 11B-303.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30909	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30910	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30974	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30975	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30976	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30977	Path of Travel	Change in Level	\$450.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31020	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31021	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31022	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31023	Path of Travel	Change in Level	\$900.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31156	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31205	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31206	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31207	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31537	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31538	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31539	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31540	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31201	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31202	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31203	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31204	Path of Travel	Change in Level	\$300.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31210	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00	ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31208	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31209	Path of Travel	Change in Level	\$450.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31235	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31236	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31196	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31195	Path of Travel	Clear Width - Walking Surfaces	\$3,500.00	ADA 403.5.1, CA 11B-403.5.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30960	Ramps	Surface Change in Level	\$1,840.00	ADA 405.7.1	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30961	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 11B-405.7.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30963	Ramps	Handrail interrupted	\$2,320.00	ADA 405, 405.8, 505.6	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30964	Ramps	Handrail Bottom Extension	\$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30965	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30966	Ramps	Handrail Bottom Extension	\$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30967	Ramps	Handrail Height	\$3,918.00	ADA 405, 405.8, 505.4, CA 11B-405.8, 505.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31285	Elevators	Evacuation Signage	\$207.00	ADA 302, 407	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31286	Elevators	Emergency System	\$800.00	ADA 407.4.6.4, CA 11B-407.4.6.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31287	Elevators	Door	\$800.00	ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31288	Elevators	Space between Car and Floor	\$1,840.00	ADA 302, 407	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31289	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31290	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31291	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31292	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30848	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30849	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30850	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30851	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30852	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30853	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30854	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30855	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30856	Stairs	Vertical Clearance Height		ADA 307.4, CA 11B-307.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30858	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30859	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30860	Stairs	Handrail Distance From Wall	\$1,916.00	ADA 504, 504.6, 505.5, CA 11B-505.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30861	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30862	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30880	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30881	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30882	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30883	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31189	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31190	Stairs	Handrail Smoothness	\$1,528.00	ADA 504.6, 505, 505.8, CA 11B-504.6, 505.8	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31191	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31192	Stairs	Handrail Smoothness	\$1,528.00	ADA 504.6, 505, 505.8, CA 11B-504.6, 505.8	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31193	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31211	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31212	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31213	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31214	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31215	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31216	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31217	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31218	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31219	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31220	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31221	Stairs	Handrail Distance From Wall	\$1,916.00	ADA 504, 504.6, 505.5, CA 11B-505.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31222	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31223	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31224	Stairs	Vertical Clearance Height		ADA 307.4, CA 11B-307.4	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31225	Stairs	Handrail on One Side	\$1,528.00	ADA 504, CA 11B-504.6, 505.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31226	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31227	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31228	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31229	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31230	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31126	Stairs	Riser Striping	\$1,000.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31142	Stairs	Landing Upper Approach Stripe	\$1,000.00	CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31127	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31128	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31129	Stairs	Handrail Extension Length	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31130	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31131	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31132	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31133	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31134	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31135	Stairs	Handrail Extension Length	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31136	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31137	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31138	Stairs	Handrail Extension Length	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31139	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31140	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31141	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31143	Stairs	Riser Striping	\$1,000.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31155	Stairs	Landing Upper Approach Stripe	\$1,000.00	CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31144	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31145	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31146	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31147	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31148	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31149	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31150	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31151	Stairs	Handrail Interrupted	\$1,840.00	ADA 504, 504.6, 505.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31152	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31153	Stairs	Is Handrail Extension Parallel	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31154	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30920	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30921	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 11B-404.2.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31028	Doors	Front Approach Latch Side Clearance	\$5,842.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31027	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31051	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31050	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31238	Doors	Door Opening Pressure	\$100.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31255	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30847	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30846	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30867	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30872	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30876	Doors	Front Approach Latch Side Clearance	\$8,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30874	Doors	Door Opening Pressure	\$50.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30875	Doors	Height	\$560.00 ADA 404, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30888	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30889	Doors	Door Hardware	\$50.00 ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30892	Doors	Floor Mat	\$126.00 ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30890	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30891	Doors	Bottom Door Panel	\$2,000.00 ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30917	Doors	Floor Mat	\$252.00 ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30918	Doors	Floor Surface Slope	\$3,000.00 ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30916	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30915	Doors	Door Opening Pressure	\$50.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30940	Doors	Automatic - Signage	\$158.00 ADA 404, ANSI/BHMA A156	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30949	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30950	Doors	Front Approach Clear Floor Space Length	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30948	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30957	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30958	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30973	Doors	Floor Mat	\$126.00 ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30970	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30971	Doors	Door Hardware	\$50.00 ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30972	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/21	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31007	Doors	Floor Surface Slope	\$1,500.00 ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31006	Doors	Door Lock	\$310.00 ADA 309.4, 404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31009	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31008	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31025	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31024	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31049	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31048	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31122	Doors	Front Approach Latch Side Clearance	\$2,921.00 ADA 404, 404.2.4, 404.2.4.1, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31121	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31125	Doors	Door Lock	\$1,550.00 ADA 309.4, 404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31237	Doors	Door Opening Pressure	\$125.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31254	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31253	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31257	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31256	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31268	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31267	Doors	Accessible Hardware	\$800.00 ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31277	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31276	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31284	Doors	Door Opening Pressure	\$50.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31293	Doors	Door Opening Pressure	\$100.00 ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30844	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30845	Counters	Knee Clearance Depth	\$1,260.00 ADA 306.3.3, 904.3.2, CA 118-306.3.3, 904.4.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30912	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30913	Counters	Knee Clearance Depth	\$1,260.00 ADA 306.3.3, 904.3.2, CA 118-306.3.3, 904.4.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30969	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31283	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31296	Counters	Counter Height	\$3,500.00 ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30968	Signage	Directional or Information Signage	\$316.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31029	Signage	Directional or Information Signage	\$158.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31120	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30878	Signage	Accessible Element/Entrance Signage	\$316.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31112	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31231	Signage	Room Identification	\$632.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30837	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30877	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30879	Signage	Room Identification	\$316.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30908	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30914	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30956	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30994	Signage	Room Identification	\$1,738.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31011	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31124	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31157	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31194	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31197	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31200	Signage	Room Identification	\$790.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31251	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31252	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30870	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30871	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30869	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30868	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30978	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30979	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30980	Restrooms	Shelf Height	\$277.00	ADA 603, 603.4	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30986	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30987	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30983	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 118-604.5, 609.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30984	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30985	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30988	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30982	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31169	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31170	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31178	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31179	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31175	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31176	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31171	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31173	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31174	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31299	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31298	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31297	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30838	Restrooms	Required Alternate Stall	\$4,000.00	ADA 213, 213.3.1, 604	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30843	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30841	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30842	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30839	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30840	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30901	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30896	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30897	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30898	Restrooms	Side Grab Bar Height	\$500.00	ADA 603, 609, 609.4, CA 11B-604.5, 609.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30899	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30900	Restrooms	Rear Grab Bar Height	\$231.00	ADA 603, 609, 609.4, CA 11B-609.4	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30902	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30893	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30895	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30991	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30992	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30993	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30990	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30989	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30995	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00	ADA 213, 213.2.1, CA 11B-213.2.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31004	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31005	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30998	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 11B-213, 309.4, 606	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30999	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31000	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31001	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31002	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31003	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30996	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30997	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31012	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00	ADA 213, 213.2.1, CA 11B-213.2.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31013	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31015	Restrooms	Lavatory Control Type	\$392.00	ADA 213, 309.4, 606, CA 11B-213, 309.4, 606	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31016	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31017	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31018	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31019	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31014	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31113	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31116	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31117	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31118	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31115	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31158	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00	ADA 213, 213.2.1, CA 11B-213.2.1	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31159	Restrooms	Circular Turning Space Diameter	\$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 11B-304.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31168	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31167	Restrooms	Door Signage	\$158.00	CA 11B-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31162	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31163	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31164	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31165	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31166	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31160	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31161	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31249	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31245	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31246	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31247	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31248	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31241	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31243	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31244	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31258	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31265	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31262	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31263	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31264	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31266	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31259	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31261	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31269	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31275	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31273	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	12/31/26	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31274	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31270	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31272	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31198	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31199	Drinking Fountains	Knee Clearance	\$2,500.00	ADA 211, 306, 602, 602.2, CA 11B-306, 602.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31239	Locker Rooms	Accessible Benches	\$500.00	ADA 222, 803, 803.4	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31240	Locker Rooms	Mirror	\$350.00	ADA 222, 803	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31294	Locker Rooms	Accessible Benches	\$500.00	ADA 222, 803, 803.4	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31295	Locker Rooms	Mirror	\$350.00	ADA 222, 803	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30836	Emergency Warning Systems	Emergency Warning System	\$2,200.00	ADA 215, 702, CA 11B-215, 702	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30941	Accessible Showers	Width	\$3,500.00	ADA 213, 608, CA 11B-608.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30945	Accessible Showers	Seat Position	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30946	Accessible Showers	Soap Dish Location	\$277.00	CA 11B-608.10	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30942	Accessible Showers	Controls	\$1,840.00	ADA 213, 608, 608.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30943	Accessible Showers	Hand Held Unit Hose Length	\$385.00	ADA 213, 608, 608.6, CA 11B-608.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31030	Accessible Showers	Width	\$3,500.00	ADA 213, 608, CA 11B-608.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31033	Accessible Showers	Seat Position	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31034	Accessible Showers	Seat Distance From Wall	\$1,500.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31031	Accessible Showers	Controls	\$1,840.00	ADA 213, 608, 608.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31032	Accessible Showers	Hand Held Unit	\$385.00	ADA 213, 608, CA 11B-608.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31037	Accessible Showers	Width	\$3,500.00	ADA 213, 608, CA 11B-608.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31042	Accessible Showers	Seat Position	\$1,068.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31043	Accessible Showers	Seat Distance From Wall	\$1,500.00	ADA 608, CA 11B-608.4, 610.3	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31041	Accessible Showers	Grab Bar is over Seat	\$1,840.00	ADA 608, 608.6, CA 11B-608.3, 609	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31038	Accessible Showers	Controls	\$1,840.00	ADA 213, 608, 608.6	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31039	Accessible Showers	Hand Held Unit Hose Length	\$385.00	ADA 213, 608, 608.6, CA 11B-608.6	Not_Started	12/31/26	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31040	Accessible Showers	Hand Held Unit Distance From Seat	\$385.00	ADA 213, 608, CA 11B-608.5	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31010	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31250	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/31	\$0.00

Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30863	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 11B-305.2	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30864	Reach Ranges	Knee Height	\$500.00	ADA 226, 304, 306, 902	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	30919	Reach Ranges	Knee Height	\$500.00	ADA 226, 304, 306, 902	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31026	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/31	\$0.00
Modesto Centre Plaza - 1000 L Street Modesto, CA 95354	31123	Reach Ranges	Knee Height	\$500.00	ADA 226, 304, 306, 902	Not_Started	12/31/31	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20357	Parking	Less Than Minimum Required Parking Spaces	\$370.00	ADA 208, 208.2, CA 11B-208.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20372	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00	CA 11B-502	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20358	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20359	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20360	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20361	Parking	Parking Space ISA Contrast	\$220.00	CA 11B-502.6.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20362	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20363	Parking	Parking Lot Warnings	\$300.00	CA 11B-502.6.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20364	Parking	Parking Space ISA Contrast	\$220.00	CA 11B-502.6.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20365	Parking	Van Accessible Signage	\$250.00	ADA 502, 502.6	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20366	Parking	Access Aisle Width	\$250.00	ADA 208, 502.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20367	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20368	Parking	Access Aisle is Faded or Damaged	\$250.00	ADA 502.3, 502.3.3, CA 11B-502.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20369	Parking	Access Aisle	\$180.00	CA 11B-502.3.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20370	Parking	Access Aisle Striping	\$350.00	CA 11B-502.3.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20371	Parking	Access Aisle - "No Parking"	\$250.00	CA 11B-502.3.3	Not_Started	12/31/24	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20373	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20374	Curb Ramps	Top Landing Slope	\$1,260.00	ADA 402.2, 406.4, CA 11B-406.5.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20416	Curb Ramps	Detectable Warnings	\$248.00	CA 11B-406.5.12, CA MUTCD	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20417	Curb Ramps	Curb Ramp Slope	\$1,300.00	ADA 405.2, 406, 406.1, CA 11B-406.2.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20348	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20349	Path of Travel	Mat or Runner	\$42.00	ADA 302, 302.2, CA 11B-302, 403.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20350	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/33	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20353	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20351	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20352	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20355	Path of Travel	Designated Accessible Route	\$1,840.00	ADA 206, 206.2, 402.1	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20356	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20375	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/33	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20378	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20379	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20429	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20475	Path of Travel	Crosswalks and Detectable Warnings	\$190.00	ADA 705, CA 11B-247.1.2.5, 705.1.2.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20473	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20474	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20483	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/33	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20484	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 118-303, 403.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20485	Path of Travel	Surface	\$1,840.00	ADA 302, 303, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/33	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20346	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20347	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20376	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20377	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20380	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20381	Doors	Latch Approach Clear Floor Space Width	\$4,000.00	ADA 404, 404.2.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20383	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20385	Doors	Latch Approach Clear Floor Space Width	\$4,000.00	ADA 404, 404.2.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20384	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20426	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20427	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20423	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20424	Doors	Bottom Door Panel Height	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20425	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20476	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 118-404.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20477	Doors	Latch Approach Clear Floor Space Width	\$4,000.00	ADA 404, 404.2.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20481	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20478	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/24	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20479	Doors	Bottom Door Panel Height	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20480	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20345	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20472	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20422	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20428	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20486	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20471	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20386	Restrooms	Door Reduces Clear Floor Space	\$1,800.00	ADA 304, 603, 603.2.3, CA 118-304.4, 603.2.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20387	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00	ADA 304, 305.3, 603.2, 603.2.3, CA 118-603.2.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20396	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20397	Restrooms	Urinal Flush Control Height	\$227.00	ADA 308.2, 309.3, 605, 605.4, CA 118-605.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20398	Restrooms	Urinal Clear Floor Space Width	\$1,707.00	ADA 305.3, 605, 605.3, CA 118-305.3, 605.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20399	Restrooms	Restroom Urinal	\$2,300.00	ADA 305, 605, 605.3, CA 118-605.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20395	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20389	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20390	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20391	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20392	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 118-305, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20393	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/24	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20394	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20400	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20401	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20388	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20402	Restrooms	Circular Turning Space Diameter	\$14,000.00 ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 118-304.3	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20412	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20413	Restrooms	Mirror Top Height	\$250.00 ADA 213, 603, 603.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20405	Restrooms	Lavatory Control Type	\$392.00 ADA 213, 309.4, 606, CA 118-213, 309.4, 606	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20406	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20407	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20408	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 118-606.6	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20409	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00 ADA 213, 305.3, 606, 606.2, CA 118-305, 606.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20410	Restrooms	Lavatory Pipes Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20411	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20414	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20415	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20403	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20404	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20430	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00 ADA 304, 305.1, 309.2, CA 118-305.1, 309.2, 603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20431	Restrooms	Toilet Paper Dispenser	\$277.00 ADA 603, 604.7, CA 118-604.7	Not_Started	12/31/24	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20432	Restrooms	Clear Space in Front of Compartment	\$4,000.00	ADA 603, 604.8.1.2, CA 11B-604.8.1.2, 604.8.2.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20433	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20434	Restrooms	Toilet Compartment Length	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20435	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20436	Restrooms	Grab Bars	\$267.00	ADA 603, 604.5, 609, CA 11B-604.5	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20443	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20444	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20445	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20446	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 11B-604.8.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20447	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20448	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20449	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20437	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20438	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20440	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20441	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20442	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20450	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00	ADA 304, 305.1, 309.2, CA 11B-305.1, 309.2, 603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20451	Restrooms	Toilet Paper Dispenser	\$277.00	ADA 603, 604.7, CA 11B-604.7	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20452	Restrooms	Clear Space in Front of Compartment	\$4,000.00	ADA 603, 604.8.1.2, CA 11B-604.8.1.2, 604.8.2.2	Not_Started	12/31/30	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20453	Restrooms	Toilet Compartment Width	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20454	Restrooms	Toilet Compartment Length	\$4,000.00	ADA 213, 603, 604, 604.8.1.1, CA 11B-604.8.1.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20455	Restrooms	Seat Cover Dispenser Height	\$277.00	ADA 205, 308, 308.2, 309, 606, CA 11B-603.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20456	Restrooms	Path of Travel width	\$2,400.00	ADA 213, 604, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20457	Restrooms	Grab Bars	\$267.00	ADA 603, 604.5, 609, CA 11B-604.5	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20470	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20463	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20464	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20465	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20466	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 11B-604.8.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20467	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20468	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20469	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20458	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20459	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20461	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20462	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/30	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20418	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 11B-211.2, 602	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20419	Drinking Fountains	Protruding Object	\$550.00	ADA 211, 305, 306, 307.2, 602, CA 11B-307.2, 602	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20420	Drinking Fountains	Clear Floor Space Slope	\$2,200.00	ADA 211, 305, 305.2, 306, 602, CA 11B-602.2	Not_Started	12/31/24	\$0.00

Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20421	Drinking Fountains	Fountain Depth	\$2,500.00	ADA 211, 305, 306, 602, CA 11B-602.8	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20482	Break/Conferenc e Room	Tables - Knee Depth	\$2,174.00	ADA 205, 228, 306.3.3, 308, 309, CA 11B-306.3.2, 306.3.3, 902.2	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20382	Picnic Areas	Accessible Route	\$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403, CA 11B-246.5, 902	Not_Started	12/31/24	\$0.00
Modesto Municipal Golf Course - 400 Tuolumne Boulevard Modesto, CA 95351	20354	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 11B-305.2	Not_Started	12/31/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25241	Elevators	Evacuation Signage	\$158.00		Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25144	Elevators	Re-opening Device	\$800.00	ADA 407, 407.3.3.2, CA 11B-407.3.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25145	Elevators	Door	\$800.00	ADA 407, 407.3.3.3, CA 11B-407.3.3.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25146	Elevators	Space between Car and Floor	\$1,840.00	ADA 302, 407	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25147	Elevators	Emergency System	\$800.00	ADA 407, 407.4.9, 708.2, CA 11B-407.4.9	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25148	Elevators	Emergency System	\$1,200.00	ADA 308, 407, 407.4.9, ASME A17.1, CA 11B-308, 407.4.9	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25149	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25150	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25151	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25152	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24593	Platform Lifts	Lowering device	\$300.00	ADA 302, 410, ASME A18.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24594	Platform Lifts	Top Landing		CA 11B-410.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24595	Platform Lifts	Bottom Landing		CA 11B-410.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24596	Platform Lifts	Landing Slope	\$1,840.00	ADA 302, 410, ASME A18.1, CA 11B-305.2, 404.2.4.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24533	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24534	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24535	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24536	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24537	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24538	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24539	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24540	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24541	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24542	Stairs	Handrail Bottom Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	6/6/29	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24543	Stairs	Handrail Extension Length	\$627.00	ADA 504, CA 11B-505.10.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24544	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24488	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24489	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24491	Doors	Door Threshold	\$257.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24507	Doors	Door Opening Pressure	\$75.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24510	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24509	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24516	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24520	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24546	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24556	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24563	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, 404.2.4.1, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24564	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24562	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24609	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24625	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24633	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24641	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24643	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25248	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24647	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24646	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24671	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24672	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24669	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24691	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24690	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24696	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24697	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24734	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24740	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24742	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24756	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24758	Doors	Door Threshold	\$257.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24759	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24760	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24780	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24806	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24812	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24838	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24849	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24850	Doors	Door Threshold	\$257.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24895	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24896	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25069	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25075	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25079	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25083	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25104	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/18	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25242	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24624	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24511	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 11B-216.3, 703.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24506	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24512	Signage	Braille	\$50.00	ADA 216, 703, 703.3, CA 11B-703.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24513	Signage	ISA Symbol	\$38.00	ADA 216, 216.6, 703, 703.7.2.1, CA 11B-216.6, 703.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24521	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24545	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24561	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	6/6/24	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	25218	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25219	Signage	Braille Location	\$158.00	ADA 307, 703.3.2, CA 11B-703.3.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25220	Signage	Braille	\$50.00	ADA 216, 703, 703.3, CA 11B-703.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25221	Signage	Raised Letters	\$50.00	ADA 216, 216.2, 703, 703.2.1, CA 11B-703.2.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25222	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25223	Signage	Braille Location	\$158.00	ADA 307, 703.3.2, CA 11B-703.3.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25224	Signage	Braille	\$50.00	ADA 216, 703, 703.3, CA 11B-703.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25225	Signage	Raised Letters	\$50.00	ADA 216, 216.2, 703, 703.2.1, CA 11B-703.2.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25226	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24881	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24891	Signage	Braille Location	\$158.00	ADA 307, 703.3.2, CA 11B-703.3.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24892	Signage	Braille	\$50.00	ADA 216, 703, 703.3, CA 11B-703.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24893	Signage	Raised Letters	\$50.00	ADA 216, 216.2, 703, 703.2.1, CA 11B-703.2.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24894	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24897	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25227	Signage	Mount Location	\$50.00	ADA 703, 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25229	Signage	Distance from Door to Center of Sign	\$158.00	ADA 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25231	Signage	Distance from Door to Center of Sign	\$158.00	ADA 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25238	Signage	Distance from Door to Center of Sign	\$158.00	ADA 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25162	Signage	Signage	\$158.00	CA 11B-504.8	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25163	Signage	Signage Height	\$158.00		Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25233	Signage	Distance from Door to Center of Sign	\$158.00	ADA 703.4.2, CA 11B-703.4.2	Not_Started	6/6/24	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	25246	Visual and Audible Communications	Assistive Listening System Signage	\$58.00	ADA 216, 219, 703, CA 11B-215.2, 907.5.2.3.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24482	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24483	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24484	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24480	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24481	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24485	Restrooms	Toilet Paper Dispenser Height	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24486	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24487	Restrooms	Distance to center of roll from floor	\$152.00	ADA 304, 604.7, CA 11B-604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24478	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24498	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24499	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24500	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24501	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24496	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24497	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24502	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24493	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24495	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24519	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24518	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24529	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24530	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24531	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24532	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24526	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24527	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24528	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24524	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24558	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	6/6/29	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24560	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24610	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00	ADA 213, 213.2.1, CA 11B-213.2.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24611	Restrooms	Circular Turning Space Diameter	\$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 11B-304.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24613	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 11B-306.3.3, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24614	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24615	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24616	Restrooms	Lavatory Clear Floor Space Width	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24617	Restrooms	Lavatory Clear Floor Space Length	\$2,261.00	ADA 213, 305.3, 606, 606.2, CA 11B-305, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24618	Restrooms	Lavatory Pipes Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24619	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24620	Restrooms	Toe Clearance	\$289.00	ADA 213, 306.2.1, 606, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24621	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24622	Restrooms	Male Restroom Signage	\$158.00	CA 11B-703.7.2.6.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24623	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24612	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24653	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24654	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24651	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24652	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24655	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24650	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24681	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24682	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24678	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24679	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24680	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24683	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24676	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24693	Restrooms	Lavatory Surface Height	\$1,286.00	ADA 213, 606, 606.3, CA 11B-213, 606.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24694	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24695	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24692	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24715	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24718	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24717	Restrooms	Lavatory Surface Height	\$1,286.00	ADA 213, 606, 606.3, CA 11B-213, 606.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24716	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24766	Restrooms	Mirror Bottom Edge Height	\$300.00	ADA 213, 603, 603.3, CA 11B-603.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24767	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24765	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24768	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24770	Restrooms	Highest Tactile Character Height	\$158.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24763	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24764	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24773	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24774	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24776	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24777	Restrooms	Highest Tactile Character Height	\$158.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24775	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24771	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24772	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24789	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24790	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24791	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24788	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24795	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24796	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24797	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24798	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24799	Restrooms	Front Approach Latch Side Clearance	\$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24794	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24804	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24803	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24805	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24800	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24802	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24828	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24829	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24830	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24831	Restrooms	Highest Tactile Character Height	\$158.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24826	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24827	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24836	Restrooms	Wall Signage	\$158.00	ADA 216, 703, 703.2.2, CA 11B-703.2	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24837	Restrooms	Highest Tactile Character Height	\$158.00	ADA 703.4.1, CA 11B-703.4.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24833	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24834	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24835	Restrooms	Male Restroom Signage	\$158.00	CA 11B-703.7.2.6.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24832	Restrooms	Dispenser Operation	\$277.00	ADA 205, 309, 309.4, CA 11B-309.4, 603.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25254	Restrooms	Toilet Clear Floor Space Width	\$1,707.00	ADA 502.4, 603, 604.3.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24857	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24854	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24855	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25255	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24852	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24853	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24882	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00	ADA 304, 305.3, 603.2, 603.2.3, CA 11B-603.2.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24883	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24884	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 11B-306.3.1, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24885	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 11B-606.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24889	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24890	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/29	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24888	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25100	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25101	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25102	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25103	Restrooms	Distance to center of roll from floor	\$152.00	ADA 304, 604.7, CA 11B-604.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25095	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25098	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25099	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25132	Restrooms	Vertical Grab Bar	\$267.00	ICC/ANSI A117.1 604.5.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25138	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25139	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25140	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25141	Restrooms	Distance to center of roll from floor	\$152.00	ADA 304, 604.7, CA 11B-604.7	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25133	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25135	Restrooms	Toilet Flush Control - Wide Side	\$127.00	ADA 603, 604.6, CA 11B-604.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25136	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25137	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25243	Drinking Fountains	Drinking Fountain	\$1,840.00	ADA 211, 305, 306, 402.1, 602, 602.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25244	Drinking Fountains	Stream Trajectory	\$2,875.00	ADA 602.6, CA 11B-602.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25239	Drinking Fountains	Stream Trajectory	\$2,875.00	ADA 602.6, CA 11B-602.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25240	Drinking Fountains	Spout Height for Standing Persons		ADA 602.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25247	Assembly Areas	Less Than Minimum Required Accessible Seats	\$600.00	ADA 221.2, 802.1, CA 11B-221.2, 802.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24574	Assembly Areas	Wheelchair Location ISA	\$50.00	ADA 216, 703, CA 11B-703.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24575	Assembly Areas	ISA Symbol	\$50.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24576	Assembly Areas	Wheelchair Location ISA	\$50.00	ADA 216, 703, CA 11B-703.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24577	Assembly Areas	ISA Symbol	\$50.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24578	Assembly Areas	Wheel Stop	\$300.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24580	Assembly Areas	Accessible Seating Information	\$207.00	ADA 221, CA 11B-216, 221	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24581	Assembly Areas	Less Than Minimum Required Accessible Seats	\$600.00	ADA 221.2, 802.1, CA 11B-221.2, 802.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24588	Assembly Areas	Wheelchair Location ISA	\$50.00	ADA 216, 703, CA 11B-703.7	Not_Started	6/6/29	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24589	Assembly Areas	ISA Symbol	\$50.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24590	Assembly Areas	Wheelchair Location ISA	\$50.00	ADA 216, 703, CA 11B-703.7	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24591	Assembly Areas	ISA Symbol	\$50.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24592	Assembly Areas	Wheel Stop	\$300.00	ADA 225, 802	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24673	Locker Rooms	ISA Symbol	\$58.00	ADA 222, 803	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24674	Locker Rooms	Bench Width	\$500.00	ADA 222, 803, 803.4, 903.3, CA 11B-803.4, 903.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24675	Locker Rooms	Bench Height	\$500.00	ADA 222, 803, 803.4, 903.5, CA 11B-222, 803.4, 903.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24814	Locker Rooms	Accessible Lockers Availability	\$1,840.00	ADA 222, 225.2.1, 803, 811, F222.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24815	Locker Rooms	Bench Width	\$500.00	ADA 222, 803, 803.4, 903.3, CA 11B-803.4, 903.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24816	Locker Rooms	Bench Height	\$500.00	ADA 222, 803, 803.4, 903.5, CA 11B-222, 803.4, 903.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25245	Emergency Warning Systems	Visual Alarms	\$2,200.00	ADA 215, 702, CA 11B-216, 221	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24579	Emergency Warning Systems	Visual Alarms	\$2,200.00	ADA 215, 702, CA 11B-216, 221	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24598	Emergency Warning Systems	Emergency Warning Systems	\$2,200.00	ADA 215, 702, CA 11B-215, 702	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25235	Emergency Warning Systems	Visual Alarms	\$2,200.00	ADA 215, 702, CA 11B-215.2, 907.5.2.3.1	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24476	Break/Conferenc e Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24550	Break/Conferenc e Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24551	Break/Conferenc e Room	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 11B-606.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24552	Break/Conferenc e Room	Pipes Wrapping	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24553	Break/Conferenc e Room	Supply Lines	\$149.00	ADA 606.5, CA 11B-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24555	Break/Conferenc e Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24554	Break/Conferenc e Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25234	Break/Conferenc e Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24632	Break/Conferenc e Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24631	Break/Conferenc e Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25158	Break/Conferenc e Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24723	Break/Conferenc e Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 11B-305, 306, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24726	Break/Conferenc e Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24725	Break/Conferenc e Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 11B-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25249	Break/Conferenc e Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24753	Break/Conferenc e Room	Break Room	\$110.00	ADA 308, 309, CA 11B-603.5	Not_Started	6/6/24	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24754	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 118-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24751	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 118-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24752	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 118-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24782	Break/Conference Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24783	Break/Conference Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 118-305, 306, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24784	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 118-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24868	Break/Conference Room	Cabinet Door Hardware	\$1,000.00	ADA 205, 228, 308, 309, CA 118-606.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24871	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 118-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24872	Break/Conference Room	Break Room	\$110.00	ADA 308, 309, CA 118-603.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24870	Break/Conference Room	Reach Height	\$1,200.00	ADA 205, 308, 309, CA 118-205, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	25256	Break/Conference Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24876	Break/Conference Room	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 118-606.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24877	Break/Conference Room	Toe Kick	\$612.00	ADA 305, 306, 606.2, CA 118-305, 306, 606.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24878	Break/Conference Room	Pipes Wrapping	\$149.00	ADA 606.5, CA 118-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24880	Break/Conference Room	Supply Lines	\$149.00	ADA 606.5, CA 118-606.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24874	Break/Conference Room	Tables - Knee Clearance	\$500.00	ADA 305, 306, 902.2, CA 118-305, 306, 902.2	Not_Started	6/6/24	\$0.00
Police Administration	24727	Lockers	Number of Accessible Lockers					
Police Administration - 600 10th street Modesto, CA 95353	24728	Lockers	ISA Symbol	\$158.00	ADA 225.2.1, 811.1	Not_Started	6/6/24	\$0.00
Police Administration	24778	Lockers	Number of Accessible Lockers					
Police Administration - 600 10th street Modesto, CA 95353	24779	Lockers	ISA Symbol	\$158.00	ADA 225.2.1, 811.1	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24820	Accessible Showers	Seat Length	\$1,068.00	ADA 608, CA 118-608.4, 610.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24821	Accessible Showers	Seat Width	\$1,500.00	ADA 608, CA 118-608.4, 610.3	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24822	Accessible Showers	Soap Dish Location	\$277.00	CA 118-608.10	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24823	Accessible Showers	Water Valve Distance From Seat Wall	\$1,500.00	ADA 213, 608, 608.6, CA 118-608.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24824	Accessible Showers	Water Valve Height	\$554.00	ADA 213, 608, 608.5, CA 118-608.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24825	Accessible Showers	Water Valve Control Type	\$554.00	ADA 213, 608, CA 118-309.4, 608.5	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24817	Accessible Showers	Hand Held Unit Height	\$385.00	ADA 213, 608, CA 118-608.5	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24818	Accessible Showers	Hand Held Unit Hose Length	\$385.00	ADA 213, 608, 608.6, CA 118-608.6	Not_Started	6/6/24	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24819	Accessible Showers	Twist Control on Hand held Mount	\$540.00	ADA 213, 608, 608.6	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24503	Reach Ranges	Clear Floor Space Slope	\$500.00	ADA 304, CA 118-305.2	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24504	Reach Ranges	Operable with one hand	\$500.00	ADA 205, 302, 308, 309, 410, CA 118-309.4	Not_Started	6/6/29	\$0.00

Police Administration - 600 10th street Modesto, CA 95353	24514	Reach Ranges	Operable with one hand	\$500.00	ADA 205, 302, 308, 309, 410, CA 118-309.4	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24515	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24565	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	6/6/29	\$0.00
Police Administration - 600 10th street Modesto, CA 95353	24599	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	6/6/29	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25127	Parking	Parking Lot Warning Sign Visibility	\$250.00	CA 118-502.8	Not_Started	6/6/24	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25114	Parking	Parking Lot Warnings	\$300.00	CA 118-502.6.2	Not_Started	6/6/24	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25108	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	6/6/24	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25109	Doors	Bottom Door Panel	\$2,000.00	ADA 404, 404.2.10, CA 118-404.2.10	Not_Started	6/6/24	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25110	Doors	Door Hardware	\$50.00	ADA 404, 404.2.10, CA 118-404.2.10	In_Progress	6/6/24	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25129	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	6/6/29	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25130	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	6/6/29	\$0.00
PROPERTY AND EVIDENCE - 1124 F ST MODESTO, CA 95351	25128	Emergency Warning Systems	Visual Alarms	\$2,200.00	ADA 215, 702, CA 118-215.2, 907.5.2.3.1	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25214	Parking	Parking Lot Warning Sign	\$250.00	CA 118-502.8	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25174	Parking	Parking Lot Warnings	\$300.00	CA 118-502.6.2	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25177	Parking	Access Aisle on Wrong side	\$250.00	ADA 502, CA 118-502.3.4	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25179	Parking	Access Aisle	\$180.00	CA 118-502.3.4	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25180	Parking	Access Aisle Striping	\$350.00	CA 118-502.3.3	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25181	Parking	Access Aisle - "No Parking"	\$250.00	CA 118-502.3.3	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25182	Parking	Parking Lot Warnings	\$300.00	CA 118-502.6.2	Not_Started	6/6/24	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25187	Parking	Access Aisle	\$180.00	CA 118-502.3.4	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25188	Parking	Access Aisle - "No Parking"	\$250.00	CA 118-502.3.3	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25190	Ramps	Ramp Run Width	\$9,515.00	ADA 405, 405.5, CA 118-405.5	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25193	Ramps	Landing Edge to Door Clearance - Side Approach	\$3,168.00	ADA 404, 405, CA 118-405.7.5	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25215	Ramps	Landing Change in Level	\$1,840.00	ADA 302, 303, 405.7.1	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25194	Ramps	Handrail Diameter	\$2,320.00	ADA 405, 405.8, 505.7.1, CA 118-405.8, 505.7	Not_Started	6/6/29	\$0.00
RANGE - MPD CROWS LANDING, CA 95350	25195	Ramps	Handrail Smoothness	\$2,200.00	ADA 405.8, 505, 505.8, CA 118-405.8, 505.8	Not_Started	6/6/29	\$0.00

RANGE - MPD RANGE CROWS LANDING, CA 95350	25196	Ramps	Handrail Interrupted	\$2,320.00	ADA 405, 405.8, 505.6	Not_Started	6/6/24	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25197	Ramps	Handrail Bottom Extension	\$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25198	Ramps	Handrail Top Extension	\$2,400.00	ADA 405, 405.8, 505.10.1, CA 11B-405.8, 505	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25199	Ramps	Handrail Near Abrasive Wall	\$2,320.00	ADA 405.8, 505, 505.8	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25200	Ramps	Handrail Diameter	\$2,320.00	ADA 405, 405.8, 505.7.1, CA 11B-405.8, 505.7	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25201	Ramps	Handrail Smoothness	\$2,200.00	ADA 405.8, 505, 505.8, CA 11B-405.8, 505.8	Not_Started	6/6/24	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25202	Ramps	Handrail Bottom Extension	\$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, CA 11B-405.8, 505.10.1	Not_Started	6/6/24	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25170	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25171	Doors	Door Lock	\$310.00	ADA 309.4, 404.2.7	Not_Started	6/6/24	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25172	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25216	Restrooms	Toilet Paper Dispenser	\$277.00	ADA 603, 604.7, CA 11B-604.7	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25206	Restrooms	Side Grab Bar Length	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25207	Restrooms	Distance Between Wall and Grab Bar	\$250.00	ADA 505, 604.9.3, 609.3, CA 11B-604.5, 609.3	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25208	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25209	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 11B-604.5.1	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25210	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25205	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25213	Break/Conference Room	Visual Alarms	\$388.00	ADA 205, 228, 308, 309	Not_Started	6/6/29	\$0.00
RANGE - MPD RANGE CROWS LANDING, CA 95350	25166	Break/Conference Room	Sink - Counter Height	\$1,800.00	ADA 606.3, CA 11B-606.3	Not_Started	6/6/29	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30412	Parking	Parking Lot Warning Sign Wording Incorrect	\$300.00	CA 11B-502	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30413	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30414	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30415	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00

Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30416	Parking	Parking Lot Warning Sign	\$250.00	CA 11B-502.8	Not_Started	12/31/26	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30395	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30396	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30397	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30398	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30399	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30400	Parking	Accessible Signage	\$250.00	ADA 502, 502.6, 703.7.2.1, CA 11B-502.6, 703.7.2.1	Not_Started	12/31/26	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30401	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30403	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30404	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30406	Parking	Access Aisle Width	\$350.00	ADA 502, 502.3.1, CA 11B-502.3.1	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30407	Parking	Access Aisle Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30408	Parking	Outline is Faded, Damaged or Missing	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/26	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30409	Parking	Parking Space Width	\$350.00	ADA 502, 502.2, CA 11B-502.2	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30410	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30411	Parking	Parking Space Slope	\$3,800.00	ADA 502, 502.4, CA 11B-502.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30388	Passenger Loading Zones	Curbs Between Access Aisle and Vehicle Pull-up Space	\$150.00	ADA 502, 503, 503.4, CA 11B-206.2.1, 303.4, 503.4	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30389	Passenger Loading Zones	Access Aisle	\$650.00	ADA 502, 503, 503.3, CA 11B-503.3	Not_Started	12/31/26	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30390	Passenger Loading Zones	Sign	\$220.00	ADA 503.3.3, CA 11B-503.6, 703.5, 703.7.2.1	Not_Started	12/31/26	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30144	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30332	Path of Travel	Grating	\$1,088.00	ADA 302, 302.3	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30393	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30356	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 11B-307.2	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30165	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00	ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30163	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30164	Path of Travel	Change in Level	\$750.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30212	Path of Travel	Protruding Objects - Vertical Clearance	\$108.00	ADA 307, 307.4, CA 11B-307.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30211	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30263	Path of Travel	Grating	\$1,088.00	ADA 302, 302.3	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30261	Path of Travel	Walking Surface Slope	\$3,600.00	ADA 402, 403.3, CA 11B-402, 403.3	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30262	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30264	Path of Travel	Walking Surface Cross Slope	\$3,600.00	ADA 402, 403.3, CA 11B-403.3	Not_Started	12/31/31	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30265	Path of Travel	Opening	\$185.00	ADA 302.3	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30266	Path of Travel	Change in Level	\$900.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Senior Center - 211								
Bodem Street								
Oroville, CA 95350	30277	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30391	Path of Travel	Change in Level	\$150.00	ADA 303, 403.4, CA 11B-303, 403.4	Not_Started	12/31/21	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30218	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 11B-206.2, 210, 402.2, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30219	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 11B-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30220	Stairs	Vertical Clearance Height		ADA 307.4, CA 11B-307.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30221	Stairs	Riser Nosing Smoothness	\$1,432.00	ADA 504, 504.5, CA 11B-504.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30222	Stairs	Risers Striping Distance From Nosing	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30223	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30224	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30225	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30226	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30227	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30228	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30229	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30267	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 11B-206.2, 210, 402.2, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30268	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 11B-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30269	Stairs	Riser Nosing Smoothness	\$1,432.00	ADA 504, 504.5, CA 11B-504.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30270	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30271	Stairs	Handrail Diameter	\$2,320.00	ADA 504.6, 505, 505.7.1, CA 11B-505.7	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30272	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30273	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30274	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30344	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 11B-206.2, 210, 402.2, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30345	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 11B-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30346	Stairs	Riser Nosing Smoothness	\$1,432.00	ADA 504, 504.5, CA 11B-504.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30347	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30348	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30349	Stairs	Handrail Extension	\$1,916.00	ADA 504, 504.6, 505.10, CA 11B-504.6, 505.10	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30350	Stairs	Handrail Extension Length	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30351	Stairs	Is Handrail Extension Parallel	\$800.00	ADA 504, 504.6, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30352	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30131	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 11B-206.2, 210, 402.2, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30132	Stairs	Stair Run Width	\$4,816.00	ADA 210, 504, CA 11B-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30133	Stairs	Vertical Clearance Height		ADA 307.4, CA 11B-307.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30134	Stairs	Riser Nosing Smoothness	\$1,432.00	ADA 504, 504.5, CA 11B-504.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30135	Stairs	Risers Height		ADA 504.2, CA 11B-504.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30136	Stairs	Risers Striping Distance From Nosing	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30137	Stairs	Risers Striping Width	\$460.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30138	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30139	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30140	Stairs	Handrail Height	\$1,528.00	ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30141	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30142	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30309	Stairs		\$4,816.00	ADA 206.2, 210, 402.2, 504, CA 11B-206.2, 210, 402.2, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30310	Stairs	Stair Run Width	\$8,572.00	ADA 210, 504, CA 11B-1009.1, 210, 504	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30311	Stairs	Handrail on One Side	\$1,528.00	ADA 504, CA 11B-504.6, 505.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30312	Stairs	Riser Tread Depth	\$8,520.00	ADA 504, 504.2, CA 11B-504.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30313	Stairs	Risers Height		ADA 504.2, CA 11B-504.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30314	Stairs	Riser Striping	\$944.00	ADA 504, CA 11B-504.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30315	Stairs	Top Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.1, 505.10.2, CA 11B-505.10.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30316	Stairs	Bottom Handrail Extension	\$1,425.00	ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30129	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30130	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30194	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30205	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30217	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30253	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30252	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30251	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30250	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30254	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30256	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30255	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30275	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30276	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30278	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30280	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30279	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30295	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 11B-302.1, 403.2	Not_Started	12/31/21	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30294	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30296	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30293	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30297	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30298	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30371	Doors	Front Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30375	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30374	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30377	Doors	Door Opening Width	\$1,750.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30378	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 11B-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30380	Doors	Door Closer Vertical Clearance	\$250.00	ADA 404, 404.2.3, CA 11B-404.2.3	Not_Started	12/31/31	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30381	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30384	Doors	Floor Mat	\$126.00	ADA 302.1, 403.2, CA 118-302.1, 403.2	Not_Started	12/31/21	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30383	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30382	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30213	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30215	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30214	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30317	Doors	Door Opening Height	\$2,000.00	ADA 307, 307.4, 404, 404.2.3, CA 118-307, 404, 404.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30319	Doors	Front Approach Clear Floor Space Length	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30318	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30307	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30308	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 118-404.2.4.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30306	Doors	Latch Approach Latch Side Clearance	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30304	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 118-404.2.7	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30305	Doors	Door Threshold	\$436.00	ADA 404, 404.2.5, CA 118-404.2.5	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30386	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30387	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30385	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 118-404.2.9	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30336	Doors	Latch Approach Clear Floor Space Width	\$2,921.00	ADA 404, 404.2.4, CA 118-404.2.4.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30355	Counters	Knee Clearance Depth	\$1,260.00	ADA 306.3.3, 904.3.2, CA 118-306.3.3, 904.4.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30394	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 118-904.4	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30166	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30182	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30184	Signage	Accessible Element/Entrance Signage	\$316.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30186	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30206	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30260	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30334	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30335	Signage	Room Identification	\$316.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30354	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30357	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30358	Signage	Room Identification	\$316.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30379	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30392	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30353	Signage	Room Identification	\$316.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30185	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30330	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 118-216.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30143	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 118-216.2, 216.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30331	Signage	Directional or Information Signage	\$158.00	ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30376	Signage	Directional or Information Signage	\$316.00 ADA 216, 216.3, 703, 703.5, CA 118-216.3, 703.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30145	Restrooms	Toilet Paper Dispenser	\$277.00 ADA 603, 604.7, CA 118-604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30146	Restrooms	Toilet Compartment Width	\$4,000.00 ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30147	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30162	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30157	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30158	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30159	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30160	Restrooms	Compartment Door Handle Height	\$269.00 ADA 213, 404, 404.2.7, 604, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30161	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30151	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30152	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00 CA 118-604.5.1	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30153	Restrooms	Side Grab Bar Height	\$500.00 ADA 603, 609, 609.4, CA 118-604.5, 609.4	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30154	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30155	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30156	Restrooms	Rear Grab Bar Height	\$231.00 ADA 603, 609, 609.4, CA 118-609.4	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30148	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30150	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30167	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30168	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30169	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30170	Restrooms	Seat Cover Dispenser Behind Toilet	\$277.00 ADA 304, 305.1, 309.2, CA 118-305.1, 309.2, 603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30171	Restrooms	Toilet Paper Dispenser	\$277.00 ADA 603, 604.7, CA 118-604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30172	Restrooms	Toilet Compartment Width	\$4,000.00 ADA 213, 603, 604, 604.8.2.1, CA 118-604.8.2.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30173	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30174	Restrooms	Side Grab Bars	\$267.00 ADA 603, 604.8.2.3, CA 118-604.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30181	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30176	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30177	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30178	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30179	Restrooms	Compartment Door Width	\$4,000.00 ADA 404, 404.2.3, 604.8, CA 118-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30180	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30190	Restrooms	Compartment Door Swings In	\$269.00 ADA 304.4, 603, 604.8, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30191	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30189	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30192	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30187	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30202	Restrooms	Urinal Rim Height	\$1,397.00 ADA 605, 605.2, CA 118-605.2	Not_Started	12/31/31	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30201	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30204	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30203	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30197	Restrooms	Lavatory Control Type	\$392.00 ADA 213, 309.4, 606, CA 118-213, 309.4, 606	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30198	Restrooms	Pedestal	\$962.00 ADA 213, 306.1, 606, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30199	Restrooms	Lavatory Surface Height	\$1,286.00 ADA 213, 606, 606.3, CA 118-213, 606.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30200	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30195	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30196	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30233	Restrooms	Toilet Compartment Width	\$4,000.00 ADA 213, 603, 604, 604.8.1.1, CA 118-604.8.1.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30234	Restrooms	Seat Cover Dispenser Height	\$277.00 ADA 205, 308, 308.2, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30235	Restrooms	Seat Cover Dispenser	\$277.00 ADA 609.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30246	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30243	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30244	Restrooms	Compartment Door Latch	\$289.00 ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30245	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30239	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30240	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00 CA 118-604.5.1	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30241	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30242	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30247	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30248	Restrooms	Toilet Paper Dispenser Interferes with Grab Bar	\$277.00 ADA 603, 609.3, CA 118-309.4, 609.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30249	Restrooms	Toilet Paper Dispenser Above Grab Bar	\$277.00 ADA 603, CA 118-604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30236	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30238	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30281	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00 ADA 304, 305.3, 603.2, 603.2.3, CA 118-603.2.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30290	Restrooms	Mirror Bottom Edge Height	\$300.00 ADA 213, 603, 603.3, CA 118-603.3	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30291	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30292	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30284	Restrooms	Lavatory Apron Height	\$2,500.00 ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30285	Restrooms	Lavatory Knee Clearance	\$1,286.00 ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30286	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00 CA 118-606.6	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30287	Restrooms	Lavatory Pipes Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30288	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30289	Restrooms	Toe Clearance	\$289.00 ADA 213, 306.2.1, 606, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30282	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30283	Restrooms	Dispenser Height	\$277.00 ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30337	Restrooms	Circular Turning Space Diameter	\$14,000.00 ADA 304, 304.3, 304.3.1, 603, 603.2.1, CA 118-304.3	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30338	Restrooms	Distance from Door Edge to Nearest Fixture	\$8,200.00 ADA 304, 305.3, 603.2, 603.2.3, CA 118-603.2.3	Not_Started	12/31/31	\$0.00

Senior Center - 211 Bodem Street Oroville, CA 95350	30340	Restrooms	Lavatory Apron Height	\$2,500.00	ADA 213, 306.3, 606, CA 118-306.3.3, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30341	Restrooms	Lavatory Knee Clearance	\$1,286.00	ADA 213, 306.3.1, 606, 606.2, CA 118-306.3.1, 606.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30342	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30343	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30339	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30362	Restrooms	Compartment Door Swings In	\$269.00	ADA 304.4, 603, 604.8, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30363	Restrooms	Compartment Door Handle Height	\$269.00	ADA 213, 404, 404.2.7, 604, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30360	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 118-604.5.1	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30361	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30364	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30128	Drinking Fountains	Knee Clearance	\$2,500.00	ADA 211, 306, 602, 602.2, CA 118-306, 602.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30257	Drinking Fountains	Fountain Type	\$2,500.00	ADA 211.2, 305, 602, CA 118-211.2, 602	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30258	Drinking Fountains	Knee Clearance	\$2,500.00	ADA 211, 306, 602, 602.2, CA 118-306, 602.2	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30259	Drinking Fountains	Stream Height	\$2,500.00	ADA 211, 602, 602.6, CA 118-211, 602	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	31536	Assembly Areas	Access to Performing Area	\$8,210.00	ADA 219, 221, 706, 802, CA 118-206.2.2, 206.2.6	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30216	Emergency Warning Systems	Emergency Warning System	\$2,200.00	ADA 215, 702, CA 118-215, 702	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30333	Break/Conference Room	Break Room - Table - Knee Width	\$2,174.00	ADA 205, 228, 308, 309	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30193	Picnic Areas	Minimum 5% Accessible	\$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30299	Reach Ranges	Reach Ranges		ADA 204, 304, 307	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30300	Reach Ranges	Element Highest Point of Operation	\$50.00	ADA 308, 309, CA 118-308, 309	Not_Started	12/31/26	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30372	Benches	On Accessible Route	\$1,840.00	ADA 205, 228, 305, 308, 309, 903	Not_Started	12/31/31	\$0.00
Senior Center - 211 Bodem Street Oroville, CA 95350	30373	Benches	Clear Floor Space	\$1,840.00	ADA 206, 305, 903.2, CA 118-206, 305, 903.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29999	Path of Travel	Clear Width - Walking Surfaces	\$3,500.00	ADA 403.5.1, CA 118-403.5.1	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29542	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 118-307.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29783	Path of Travel	Clear Width - Walking Surfaces	\$3,500.00	ADA 403.5.1, CA 118-403.5.1	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29426	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 118-307.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29246	Path of Travel	Clear Width - Walking Surfaces	\$3,500.00	ADA 403.5.1, CA 118-403.5.1	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29379	Path of Travel	Protruding Objects - Protrusion Limit	\$640.00	ADA 307, 307.2, CA 118-307.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29648	Ramps	Ramp Run Slope	\$3,600.00	ADA 405, 405.2, CA 118-405.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29649	Ramps	Landing Edge to Door Clearance - Side Approach	\$3,168.00	ADA 404, 405, CA 118-405.7.5	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29650	Ramps	Bottom Landing Length	\$2,872.00	ADA 405, 405.7.3, CA 118-405.7.3.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29651	Ramps	Landing Slope	\$2,872.00	ADA 402, 405.7.1, CA 118-405.7.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30017	Elevators	Evacuation Signage	\$158.00		Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30024	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30025	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30026	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30027	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30028	Elevators	Elevator - Jamb Marking	\$180.00	ADA 407	Not_Started	12/31/26	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30029	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30030	Elevators	Highest Tactile Character Height Above Finish Floor	ADA 703.4.1, CA 11B-703.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30031	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30032	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30033	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30034	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30043	Elevators	Evacuation Signage	\$158.00	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30047	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30048	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30049	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30050	Elevators	Highest Tactile Character Height Above Finish Floor	ADA 703.4.1, CA 11B-703.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30051	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30052	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30053	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30054	Elevators	Elevator - Jamb Marking	\$180.00 ADA 407	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29274	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29275	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29709	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29710	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29711	Stairs	Handrail Bottom Extension	\$1,425.00 ADA 504, 504.6, 505.10.3, CA 11B-505.10.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29869	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29874	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29877	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29878	Stairs	Landing Upper Approach Stripe	\$460.00 ADA 904, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29879	Stairs	Risers Striping Distance From Nosing	\$460.00 ADA 504, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29881	Stairs	Landing Upper Approach Stripe	\$460.00 ADA 904, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29882	Stairs	Landing Upper Approach Stripe	\$460.00 ADA 904, CA 11B-504.4.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29880	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29926	Stairs	Handrail Height	\$1,528.00 ADA 504, 504.6, 505.4, CA 11B-504.6, 505	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29252	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29254	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29253	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29256	Doors	Automatic - Signage	\$158.00 ADA 404, ANSI/BHMA A156	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29257	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29258	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29306	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29308	Doors	Front Approach Latch Side Clearance	\$4,000.00 ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29307	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29309	Doors	Door Threshold	\$436.00 ADA 404, 404.2.5, CA 11B-404.2.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29310	Doors	Door Opening Pressure	\$25.00 ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29671	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29685	Doors	Floor Surface Slope	\$1,500.00	ADA 302, 305, 404, 404.2.4.4, CA 11B-404.2.4.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29684	Doors	Front Approach Latch Side Clearance	\$4,000.00	ADA 404, 404.2.4, CA 11B-404.2.4.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29686	Doors	Front Approach Clear Floor Space Length	\$2,921.00	ADA 404, 404.2.4, CA 11B-404.2.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29682	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29683	Doors	Height	\$280.00	ADA 404, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29689	Doors	Door Opening Pressure	\$100.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29696	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29913	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29940	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29967	Doors	Accessible Hardware	\$800.00	ADA 309.4, 404.2.7, CA 11B-404.2.7	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29968	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29978	Doors	Door Opening Pressure	\$25.00	ADA 404.2.9, CA 11B-404.2.9	In_Progress	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29278	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29956	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29781	Counters	Counter Length	\$545.00	CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29982	Counters	Counter Length	\$545.00	CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29364	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29366	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29574	Counters	Counter Length	\$545.00	CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29133	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29134	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29178	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29179	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29187	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29214	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29382	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29654	Counters	Counter Height	\$3,500.00	ADA 902, 904, CA 11B-904.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29655	Counters	Protruding Object	\$450.00	ADA 307.2, 902	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29255	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29259	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29276	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29277	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29312	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29315	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29316	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29852	Signage	Accessible Element/Entrance Signage	\$632.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29628	Signage	Accessible Element/Entrance Signage	\$158.00	ADA 216.2, 216.6, CA 11B-216.2, 216.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29652	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29653	Signage	Room Identification	\$158.00	ADA 216, 216.2, 703, CA 11B-216.2	Not_Started	12/31/26	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29632	Visual and Audible Communications	Assistive Listening System Signage	\$58.00	ADA 216, 219, 703, CA 11B-215.2, 907.5.2.3.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29281	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29282	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29279	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29287	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29288	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29285	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29286	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29283	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29295	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29298	Restrooms	Wall Signage	\$158.00	ADA 216, 216.8, 703, CA 11B-216.8	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29296	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29297	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29294	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29303	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29304	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29301	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29302	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29305	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29299	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29300	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 11B-604.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29861	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29862	Restrooms	Toilet Compartment Door	\$4,000.00	ADA 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29859	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29860	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29863	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29857	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29918	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29921	Restrooms	International Symbol of Accessibility	\$158.00	ADA 216, 216.8, 703, 703.7, CA 11B-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29922	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29919	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29920	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29917	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29946	Restrooms	International Symbol of Accessibility	\$158.00	ADA 216, 216.8, 703, 703.7, CA 11B-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29947	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29944	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29945	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29943	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29950	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29951	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 118-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29952	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29953	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29954	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29949	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29974	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29972	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29973	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29975	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29969	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29754	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 118-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29755	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29753	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29756	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29752	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29763	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29764	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29760	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29761	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29762	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29758	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29779	Restrooms	Contrasting Finish	\$170.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29780	Restrooms	Pictogram Length		ADA 703.6.1, CA 118-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29778	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29790	Restrooms	Pictogram Length		ADA 703.6.1, CA 118-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29788	Restrooms	Door Signage Height	\$158.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29789	Restrooms	Contrasting Finish	\$170.00	CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29787	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29786	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 118-603.5	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29834	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29831	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29832	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29833	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29835	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29829	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29433	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29434	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30061	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30062	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29436	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29428	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29493	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29494	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29491	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29492	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29496	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29489	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29547	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29549	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29550	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29546	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29565	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29567	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29566	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29564	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29563	Restrooms	Dispenser Height	\$277.00	ADA 205, 308, 308.1, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29578	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29579	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29577	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29576	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 11B-604.8.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29325	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29323	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29324	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29322	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29390	Restrooms	Urinal Rim Height	\$1,397.00	ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29391	Restrooms	Door Signage Height	\$158.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29392	Restrooms	Contrasting Finish	\$170.00	CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29393	Restrooms	Pictogram Length		ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29389	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29410	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29411	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29407	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29408	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29409	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29405	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29517	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29513	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29514	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 118-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29515	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29516	Restrooms	Door Handle	\$129.00	ADA 213, 404, 604, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29512	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29519	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29511	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29557	Restrooms	Compartment Door Handle	\$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29558	Restrooms	Compartment Door	\$269.00	ADA 404, 604.8, 604.8.1.2, CA 118-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29554	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29555	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29556	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29560	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29552	Restrooms	Toilet Distance From Wall	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29152	Restrooms	Pictogram Length		ADA 703.6.1, CA 118-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29151	Restrooms	Door Signage	\$158.00	CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29150	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29169	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29165	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29166	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 118-604.5.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29167	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29168	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29170	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29164	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00	ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29186	Restrooms	Pictogram Length		ADA 703.6.1, CA 118-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29185	Restrooms	Door Signage	\$158.00	CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29183	Restrooms	Lavatory Distance From Wall/Fixture	\$2,500.00	CA 118-606.6	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29184	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00	ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29219	Restrooms	Coat Hook Height	\$50.00	ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29217	Restrooms	Rear Grab Bar Length	\$267.00	ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29218	Restrooms	Rear Grab Bar Location	\$267.00	ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29220	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29215	Restrooms	Toilet Seat Height	\$1,707.00	ADA 603, 604.4, CA 118-604.4	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29371	Restrooms	Compartment Door Width	\$4,000.00	ADA 404, 404.2.3, 604.8, CA 118-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29372	Restrooms	Compartment Door Latch	\$289.00	ADA 309.4, 404, 404.2.7, 604.8, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29369	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00	ADA 603, 604.5.1, 609, CA 118-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29370	Restrooms	Distance from Front Edge of Toilet to Front of Grab Bar	\$267.00	CA 118-604.5.1	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29374	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00	ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29368	Restrooms	Toilet Clear Floor Space	\$3,500.00	ADA 603, CA 118-604.8.1	Not_Started	12/31/31	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29386	Restrooms	Pictogram Length	ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29384	Restrooms	Door Signage Height	\$158.00 CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29385	Restrooms	Contrasting Finish	\$170.00 CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29383	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29445	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29442	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29443	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29444	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29447	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29440	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29530	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29531	Restrooms	Compartment Door	\$269.00 ADA 404, 604.8, 604.8.1.2, CA 11B-604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29527	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29528	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29529	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29525	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29570	Restrooms	Urinal Rim Height	\$1,397.00 ADA 605, 605.2, CA 11B-605.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29573	Restrooms	Pictogram Length	ADA 703.6.1, CA 11B-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29571	Restrooms	Door Signage Height	\$158.00 CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29572	Restrooms	Contrasting Finish	\$170.00 CA 11B-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29569	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29592	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29593	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29594	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29590	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29604	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 11B-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29601	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 11B-604.5.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29602	Restrooms	Rear Grab Bar Interferes	\$231.00 ADA 609.3, CA 11B-609.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29603	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 11B-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29605	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29598	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29600	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 11B-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29618	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29619	Restrooms	Compartment Door Width	\$4,000.00 ADA 404, 404.2.3, 604.8, CA 11B-404.2.3, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29620	Restrooms	Door Handle	\$129.00 ADA 213, 404, 604, 604.8.1.2, CA 11B-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29621	Restrooms	Front Approach Latch Side Clearance	\$2,200.00 ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2, CA 11B-404, 604.8.1.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29617	Restrooms	Distance from Back Wall to Front of Grab Bar	\$267.00 ADA 603, 604.5.1, 609, CA 11B-604.5.1, 609	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29622	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 11B-309.4, 604.7	Not_Started	12/31/31	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29664	Restrooms	Compartment Door Handle	\$250.00 ADA 213, 404, 604, 604.8, 604.8.1.2, CA 118-404.2.7, 604.8.1.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29662	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29663	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29676	Restrooms	International Symbol of Accessibility	\$158.00 ADA 216, 216.8, 703, 703.7, CA 118-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29677	Restrooms	Pictogram Length	ADA 703.6.1, CA 118-703.6.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29674	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29675	Restrooms	Contrasting Finish	\$170.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29673	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29679	Restrooms	Door Signage Height	\$158.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29680	Restrooms	Contrasting Finish	\$170.00 CA 118-703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29681	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29678	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29691	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00 ADA 213, 213.2.1, CA 118-213.2.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29695	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29694	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29692	Restrooms	Lavatory Surface Height	\$1,286.00 ADA 213, 606, 606.3, CA 118-213, 606.3	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29693	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29865	Restrooms	Door Privacy Lock and Occupied Indicator	\$804.00 ADA 213, 213.2.1, CA 118-213.2.1	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29868	Restrooms	Wall Signage	\$158.00 ADA 216, 216.8, 703, CA 118-216.8	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29867	Restrooms	Door Signage	\$158.00 CA 118-216.8, 703.7.2.6	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29866	Restrooms	Lavatory - Supply Lines Wrapping	\$149.00 ADA 213, 606, 606.5, CA 118-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29900	Restrooms	Coat Hook Height	\$50.00 ADA 308, 308.1, 603.4, CA 118-308, 603.4, 604.8.3	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29898	Restrooms	Rear Grab Bar Length	\$267.00 ADA 603, 604.5.2, 609, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29899	Restrooms	Rear Grab Bar Location	\$267.00 ADA 604.5.2, CA 118-604.5.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29901	Restrooms	Toilet Paper Dispenser Distance From Seat	\$277.00 ADA 603, 604.7, CA 118-309.4, 604.7	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29895	Restrooms	Toilet Distance From Wall	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29897	Restrooms	Toilet Minimum Distance From Any fixture	\$2,500.00 ADA 603, 604.2, CA 118-604.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29317	Drinking Fountains	Stream Height	\$2,500.00 ADA 211, 602, 602.6, CA 118-211, 602	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29825	Drinking Fountains	Knee Clearance	\$2,500.00 ADA 211, 306, 602, 602.2, CA 118-306, 602.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29633	Assembly Areas	Wheelchair Location ISA	\$50.00 ADA 216, 703, CA 118-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29634	Assembly Areas	Wheelchair Location	\$1,840.00 ADA 225, 802	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29635	Assembly Areas	ISA Symbol	\$50.00 ADA 225, 802	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29636	Assembly Areas	Wheel Stop	\$300.00 ADA 225, 802	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29637	Assembly Areas	Wheelchair Location ISA	\$50.00 ADA 216, 703, CA 118-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29638	Assembly Areas	Wheelchair Location	\$1,840.00 ADA 225, 802	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29639	Assembly Areas	ISA Symbol	\$50.00 ADA 225, 802	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29641	Assembly Areas	Wheel Stop	\$300.00 ADA 225, 802	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29642	Assembly Areas	Wheelchair Location ISA	\$50.00 ADA 216, 703, CA 118-703.7	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29640	Outdoor Sports Areas	Wheelchair Location Slope	\$1,840.00 ADA 402, CA 118-802.1.1	Not_Started	12/31/31	\$0.00

Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29700	Break/Conference Room	Pipes Wrapping	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29701	Break/Conference Room	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29705	Break/Conference Room	Break Room	\$110.00 ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29706	Break/Conference Room	Break Room	\$110.00 ADA 308, 309, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29697	Break/Conference Room	Tables - Knee Depth	\$2,174.00 ADA 205, 228, 306.3.3, 308, 309, CA 11B-306.3.2, 306.3.3, 902.2	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29836	Sinks	Pipes Wrapping	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29839	Sinks	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29840	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29842	Sinks	Pipes Wrapping	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29844	Sinks	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29845	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29846	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29503	Sinks	Pipes Wrapping	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29507	Sinks	Supply Lines	\$149.00 ADA 606.5, CA 11B-606.5	Not_Started	12/31/22	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29508	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29509	Sinks	Sink	\$180.00 ADA 205, 308, 309, 606, CA 11B-603.5	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29293	Reach Ranges	Element Highest Point of Operation	\$50.00 ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29791	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	30000	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29773	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29774	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/31	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29777	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29851	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29230	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29646	Reach Ranges	Knee Height	\$500.00 ADA 226, 304, 306, 902	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29647	Reach Ranges	Element Highest Point of Operation	\$50.00 ADA 308, 309, CA 11B-308, 309	Not_Started	12/31/26	\$0.00
Tenth Street Place - 1010 Tenth Street Modesto, CA 95354	29672	Reach Ranges	Reach Depth	\$550.00 ADA 308	Not_Started	12/31/26	\$0.00
				\$4,303,553.00			\$1,232.00